

08/11/23

SMT

ASS. REC. BY:

REF:

093/LPC22008063/Sg/3+

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s K&M Leasing

of _____

Insured: LPC

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: ISUZU

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: ~~\$11K~~ \$11K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: XD 2975T Yr Regn: 08/sep/2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ Truck / Trailer or tipper truck

Make: ISUZU cy2521 cc 15681

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 176083 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3ALCY252L8 7000068

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: ☒ S/Rim / STD A/Rim or

Tyre Size: F: 295/80R22.5

R: 295/80R22.5

BS/DUN/EXNOVA/GY/FS/LZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or elostar & Kpatox

Front 8 mm R/Bal. 7/7 mm

L/Bal. 8 mm L/Bal. 7/7 mm

D.O.A. 06/07/22 D.O.L. 23/08/22

Survey held at K&M Leasing

Des. of Damages: Frt / Rst / O/S / N/S / U/C / Rooftop or

PMA

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Date mfg
	50% depre for PMA (12/09/2016)
000000	
= 60K	60K / 2 = 30K
	Price will be reviewed on any supporting
	Doc. 13/12/23
	INV: \$11K
	NV: \$8400

Date/Time, File Pass to?

13/12/23 ☐ : Prel. Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 30000Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

13/07/23 submit \$30K, 4 days (red & 30,000, 50%)



SAFEPROTECH MANAGEMENT PTE LTD
35 WOODGROVE AVE
SINGAPORE 738231
CO REG NO: 202012496W
GST Reg No: 202012496W
CONTACT: +65 63518288
EMAIL: ADMIN@SAFEPROTECH.COM.SG

To: Jack Wong
Fit Transport Systems Pte Ltd
35, Ubi Crescent #03-01
Singapore 408585

QUOTATION

Quote No : SPT/Q/2208/07

Date : 24/08/2022

Description	Qty	UOM	AMOUNT
Supply and install new set of SS180M TMA	1.00	No	\$ 65,000.00
less: Good will discount			-\$ 5,000.00
Vehicle no: XD2975T			
		Grand Total	\$ 60,000.00

Terms & Conditions:

- Expected delivery time - 3-4 weeks
- Payment: 30% upon confirmation, 70% cash on delivery
- The above quotation is subjected to 7% GST
- An administrative fee of \$3000 (before GST) will be imposed on any cancellation of confirmed order.

E. & O.E

Validity: 14 days from the date of issue of this quotation.

Prepared By: [Signature]

Accepted by: _____

Name: Liling
Designation: Marketing Specialist
Date: 24/8/2022

Name: _____
Designation: _____
Date: _____
Company Stamp: _____

Dimpled TMA is
2016 and it is
the new model.
Account 2022.
250 applied 50% dep

Our recommendation as TMA ~~price~~ cost is subjected
to review & upon receipt of additional documents
that may be forthcoming.