

08/11/13 Wef

ASS. REC. BY: Rasm

REF:

CS/EH/22012016/Rqy3

255R

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD ☐ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To inspect Vehicle No: XE 6697P

at Workshop n/s Woon menh

of BURIT BAYOR CRESCENT

Insured: EH1

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 2500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 186K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Turn Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIM IT - 147K

Rasul re-finalised final fig \$25059.96, 10 days. (Red \$6758.40, 21%)

Veh No: XE 6697P Yr Regn: 2021 / Aug

Type: ☒ M. Car ☐ M. Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

☒ Truck ☐ Trailer or

Make: SCANIA P410A 4X2N2 CC 12742

Colour: MULTI A/C: ☒ Insured ☐ Std ☐ N/A

Sp. Reading 106880 T/Radio: ☒ Insured ☐ Std ☐ N/A

Eng No: _____

C/No: 452P4X20005626229

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ Burnt

Steering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or

Brake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or

Modi: ☒ Air ☐ S/Rim ☐ STD A/Rim or

Tyre Size: F: 315/80R22.5

R: _____

BS / ☒ DUN ☐ EXNOVA ☐ GY / FS ☐ LIZA ☐ MIC ☐ OHTSU ☐ PIR ☐ SUMI

TOYO / YOKO or

Front

R/Bal: 8 mm

L/Bal: 8 mm

D.O.A. 26/4/22

Survey held at Woon menh

Des. of Damages: ☒ Fnt ☐ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

PRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prefl. Report

1) 16/06 Typist

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 10

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : MER-OD

Temp Sum / I.B.I. (\$ 25059.96)

Woon Meng Motor Pte Ltd (Co.Reg.No:200603678M)

50 Bukit Batok Street 23,, #01-06 Midview Building

Singapore 659578

Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg

INSURER: ERGO Insurance Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCG22009586	Date of Loss:	26/11/2022
Vehicle Reg. No.:	XE6697P	Driveable?	
Driver Age/Info:	25 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CALL LADE ENTERPRISES PTE LTD		
Driver:	CHINNATHAMBI MURUGESH		

Make/Model:	SCANIA P410A4X2NZ, 12.7 D (M)	Vehicle Reg. Date:	30/08/2021
Vehicle Colour:	WHITE/RED		
Engine No:	DC13163L017299364	Chassis No:	YS2P4X20005626229
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	25

Present Location:	WOON MENG MOTOR PTE LTD (BUKIT BATOK)
-------------------	---------------------------------------

COST OF CLAIMS

	Amount
Parts	20,756.80
Miscellaneous Items	222.96
Labour	5,810.00
Paintwork Labour	1,400.00
Towing	0.00
Gross Total (\$\$)	28,189.76
+ GST 7.00% (\$\$)	1,973.28
Nett Amount (\$\$)	30,163.04

This claim is handled by: HENG SEW SOW

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Nov 2022)
 Parts: N/A SCANIA P410A4X2NZ 12.7 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Woon Meng Motor Pte Ltd/XE6697P/30/11/2022 19:02

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

7:03 PM
 Estimates on
 Qty Particulars
 1 1
 2 1
 3 1
 4 1
 5 1
 6 1
 7 1
 8 1
 9 1
 10 1
 11 1
 12 1
 13 1
 14 1
 15 1
 16 1
 17 1
 18 1
 19 1
 20 1
 21 1
 22 1
 23 1
 24 1
 25 2
 26 1
 27 1
 28 1
 29 2
 30 1
 31 1
 32 1
 33 1
 34 1
 35 4
 36 1
 37 1

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN GLASS <i>CRN</i>	0.00	0.00	*862.84 F
2	1		*FRONT SUNVISOR TOP <i>CRN</i>	0.00	0.00	*224.36 F
3	1		*FRONT SUNVISOR LOWER <i>CRN</i>	0.00	0.00	*266.88 F
4	1		*FRONT TOP MIRROR <i>bro</i>	0.00	0.00	*375.48 F
5	1		*FRONT WIPER LOWER SIDE GARNISH LH <i>MIS</i>	0.00	0.00	*87.35 F
6	1		*FRONT PANEL <i>SCN</i>	0.00	0.00	*1,058.93 F
7	1		*SCAN <i>SCN</i>	0.00	0.00	*61.24 F
8	1		*IA <i>SCN</i>	0.00	0.00	*51.85 F
9	1		*FRONT PANEL SIDE GRILLE <i>SCN</i>	0.00	0.00	*90.85 F
10	1		*FRONT LOWER PANEL <i>SCN</i>	0.00	0.00	*637.98 F
11	1		*FRONT INNER PANEL	0.00	0.00	*2,085.89 F
12	1		*COVER <i>CRN</i>	0.00	0.00	*86.70 F
13	1		*FRONT PANEL LOCK LH	0.00	0.00	*39.20 F
14	1		*FRONT CORNER PANEL LH <i>bug</i>	0.00	0.00	*675.68 F
15	1		*FRONT HEADLAMP LH <i>CRN</i>	0.00	0.00	*1,339.52 F
16	1		*FRONT HEADLAMP GRILLE LH <i>bt</i>	0.00	0.00	*128.51 F
17	1		*FRONT HEADLAMP MEAT LH <i>bt</i>	0.00	0.00	*202.66 F
18	1		*FRONT HEADLAMP GRILLE SIDE COVER LH <i>CRN</i>	0.00	0.00	*15.61 F
19	1		*FRONT BUMPER <i>bt</i>	0.00	0.00	*3,247.19 F
20	1		*FRONT BUMPER SIDE COVER LH <i>SCN</i>	0.00	0.00	*50.87 F
21	1		*FRONT FOG LAMP COVER LH <i>SCN</i>	0.00	0.00	*28.52 F
22	1		*FRONT HEADLAMP MEAT HINGE LH	0.00	0.00	*17.02 F
23	1		*FRONT CORNER PANEL BRACKET LH <i>bt</i>	0.00	0.00	*68.23 F
24	1		*FRONT CORNER PANEL SEAL LH <i>na</i>	0.00	0.00	*75.49 F
25	2		*FRONT CORNER PANEL BRACKET LH <i>bt</i>	0.00	0.00	*128.74 F
26	1		*FRONT DOOR LH <i>bug</i>	0.00	0.00	*3,427.32 F
27	1		*FRONT DOOR SIDE SEAL LH <i>na</i>	0.00	0.00	*45.12 F
28	1		*FRONT DOOR LOCK LH	0.00	0.00	*330.48 F
29	2		*FRONT DOOR HINGE LH	0.00	0.00	*279.58 F
30	1		*FRONT DOOR INNER TRIM LH	0.00	0.00	*840.04 F
31	1		*FRONT DOOR RUBBER LH	0.00	0.00	*283.05 F
32	1		*FRONT STEP PANEL LH <i>CRN</i>	0.00	0.00	*786.99 F
33	1		*FRONT HEADLAMP BRACKET LH	0.00	0.00	*154.02 F
34	1		*FRONT HEADLAMP SEAL LH	0.00	0.00	*24.72 F
35	4		*FRONT TOP MIRROR NOISE ABSORBENT <i>CRN</i>	0.00	0.00	*69.56 F
36	1		*FRONT SUNVISOR SIGNAL LAMP LH <i>MIS</i>	0.00	0.00	*91.06 F
37	1		*ROOF TOP PANEL LH <i>bt</i>	0.00	0.00	*630.29 F

F=Franchise part.

Sub Total (\$\$) 18,869.82
 + Margin on L,N Items 10.00% (\$\$) 1,886.98
 Total Parts (\$\$) 20,756.80

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRONT ERP BRACKET <i>new</i>	
2	1	FRONT WINDSCREEN SEALANT <i>m</i>	15.00
			207.96
Sub Total (\$)			222.96

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 TO PUTTY & SPRAY PAINTING

New *1000* 1,400.00Labour Items

2 TO REMOVE, REPLACE, REPAIR & REFIX DAMAGED PARTS

New *2800* ~~2400~~ 3,500.00

3 TO R & R ROOF TOP INNER TRIM

New *200* 300.004 TO R & R FRONT DASHBOARD *photo?*New *350* 450.00

5 TO REMOVE & INSTALL DOOR MECHANISM & CHECK FOR FUNCTION

New *100* 250.00

6 TO R & R FRONT WINDSCREEN GLASS

New *300* 350.007 TO R & R DRIVER SEAT AND PASSENGER SEAT *?*New *200* 280.00

8 TO R & R WIRING

New *600* 80.00

9 TO NUMBERING LOGO

New 600.00

Gross Labour Cost (\$)

7,210.00

Woon Meng Motor Pte Ltd/XE6697P/30/11/2022 19:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

10 ~~days~~

P/P

01/12/22 @ 1545

EXCESS: 2500

Repair
Resurvey before paint

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/11/2022 18:19 (SGT)
Reported by	Owner
Date of Accident	26/11/2022 05:30 (SGT)
Exact Location of Accident	Jln Buroh, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE6697P
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	CALL LADE ENTERPRISES PTE LTD
Company Reg No	1XXXXX755R
Email Address	MATTHEW@CALLADE.COM
Mobile Phone No	(Phone) +65-90490359
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Scania
Model	P410A4X2NZ
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	12742

INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Policy Number / Cover Note Number	DMCG22009586

DRIVER

Name of Driver	CHINNATHAMBI MURUGESH
Passport No/FIN	GXXXX011T
Date Of Birth	13/04/1997
Occupation	Outdoor

Date Of Driving Pass	05/08/2020
Driving experience	2 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98650698
Alt. Phone Number	-
Email Address	MATTHEW@CALLADE.COM
Address	23 TELOK BLANGAH CRESCENT
Address complement	#04-38
Postcode	090023
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bukit Merah East Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18002369999
Alt. Police Station Phone No	(Fax) +65-62204360
Police Station Address	391 New Bridge Road Police Cantonment Complex Block A Singapore 088762
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	-
Vehicle Manufacturer	-
Vehicle Model	-



Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Government
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

5. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



26/11/2022

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Describe Circumstances of the Accident

LICENSE PLATE: XE 6697 P ACCIDENT DATE & TIME: 26 Nov 2022 0350hrs
 CONTACT NUMBER: 90490359 E-MAIL ADDRESS: matthew@callade.com
 LOCATION: Jalan Buroh.

I was travelling from PSA Tuas Terminal towards Pahr Panjung
 when I lost control of my vehicle XE6697P along Jalan Buroh
 and hit a lamp post.

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN
 OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

Please state

☒ Claim Own Policy

☐ Claim Third Party

☒ Claim/OD/TP at other workshop

☒ Reporting Only

Declaration

We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date &
 Time

Driver's Signature (If driver is not the policyholder) / Date
 & Time

Witnessed by Reporting Centre
 Personnel



**SINGAPORE
POLICE FORCE**



T/20221126/2046

Police Station Of Origin:
Bukit Merah East N.P.C
391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

1 of 3

Report No T/20221126/2046

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/11/2022 13:43	Video Report No.: D/20221126/0050	Station Diary No.: 48
--	--------------------------------------	--------------------------

Informant's Particulars

Name of Informant: CHINNATHAMBI MURUGESH			Address: APT BLK 65 NEW UPPER CHANGI ROAD #02-1138 SINGAPORE 460065	
ID Type / ID No.: FIN NO / G8537011T			Contact No.: Home/Office: Mobile, 98650698	
Nationality: INDIAN			Email:	
Sex: Male	Age: 25	Date of Birth: 13/04/1997	Type of Informant: Driver	
Race: Indian			Language: English	Institution / School Name:
Occupation: Trailer-truck driver			Driving Licence Information: Class: 28,3,4	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 26/11/2022 05:30	Type of Location: Straight Road
Location: JALAN BUROH				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit: 50 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Moving Vehicle Against - Lamp Post				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
XE6697P	Lorry	SCANIA	P410A4X2N Z		Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20221126/2046

Police Station Of Origin:
Bukit Merah East N.P.C
391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

2 of 3

Report No. T/20221126/2046

CONTINUATION OF REPORT

Driver			
Name	CHINNATHAMBI MURUGESH	ID No.	G8537011T
Related Vehicle	NIL	Contact No.	98650698
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of injury	NIL

Brief Details.

On 26/11/2022, at about 0530hrs, I was driving from PSA Tuas to PSA Pasir Panjang terminal. The floor was wet and there was some light rain. Along Jln Buroh towards West Coast Rd, I was driving along the 4th lane and suddenly lost control of the vehicle and crash into the lamp post. I came out of the vehicle and called my company and the police.

The vehicle suffered a dented bumper and smashed windscreen. I was not injured from this incident and did not collide into any other vehicle. There was an in-vehicle camera at the front. The police advised me to lodge a police report as the accident involves government property.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Bukit Merah East N.P.C
391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No. 1800-2369993



1202211262046

Report No. T202211262046

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:

A /

SGT 1 LOTUS TAN LER SZE

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
STAFF SGT SYED MUHAMMAD ISA BIN
OMAR ALHABSHEE
Contact No.: 65476187

NP168

Signature Of Informant

Date/Time
26/11/2022 13:43

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	755R
Vehicle No.:	XE6697P
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Dec 2022
Vehicle Make:	SCANIA
Vehicle Model:	P410A4X2NZ
Primary Colour:	Multicolor
Manufacturing Year:	2021
Engine No.:	DC13163L017299364
Chassis No.:	YS2P4X20005626229
Maximum Power Output:	-
Open Market Value:	\$107,401.00
Original Registration Date:	30 Aug 2021
First Registration Date:	30 Aug 2021
Transfer Count:	0
Actual ARF Paid:	\$5,371.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	29 Aug 2031
COE Category:	C - Goods Vehicle & Bus
COE Period (Years):	10
QP Paid:	\$37,000.00
COE Rebate Amount:	\$32,335.00
Total Rebate Amount:	\$32,335.00

The information contained herein is correct as at 02 Dec 2022

OK