

ASS. REC. BY:

REF: ASM/ 22012035/1K2

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

GIA / PR Seen: _____

Est. Repairs: _____

Lum Sum: _____

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

No documents given PRS

1/12 En repair con 87-8K

mo, File Pass to?

☐

: Prell. Report

no, File Return to?

☐

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee: _____

Transportation

S - RS - SI

Fees

Others

TOTAL

Format:

um / I.B.I: (\$

Veh No: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STP / Rlm or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooflop or

The UIC / Chassis frame / Body Structure affected due to collision.

SUS 6006 X Yr Regn: 06, 17

Truck / Trailer or

Make: BMW 530i

Colour: M. Grey

Sp. Reading: 53911

Eng/No: _____

C/No: WBA JA 520 506 885635

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STP / Rlm or

Tyre Size: F: Nil

R: 245/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 30/11/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooflop or

The UIC / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 1/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooflop or

The UIC / Chassis frame / Body Structure affected due to collision.