ASS. REC. BY: REF: F62/2	20120421Km
MENNETH	IGNMENT
From: Date:	Veh No: SKN1213 Str Regn: 09, 14 Type: MCQR/ M Cycle / Rug (Ver 1)
Estimated Cost:	Type: M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No:	Make: No. 350 c.c 2987 Colour N. Black AC: Insured States AL
at Workshop m/s Cartimes	Colour M. Black AC: Insured / Std / NI / NA
Insured:	Sp.Reading 534446 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CANO: WDD 22213 22:A 086453
Sum Issue	Cent. Cond Sood / Fair / Poor / Burnt
(Client's Record)	Steering: Ino der / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Ingider / Jammed / Leaked / Burnt or
	Modi: NII / S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F: 245/50R18
Remark: The veh had commenced by	R:
repair at the time of inspection.	BS / DUN / EXNOVA GY FS / LIZA / MIC / OHTSU / PIR / SUMI /
Ball or Market Value: \$ // 6/c	TOYO/YOKO or
IDAC Accident Roort: Consistent 2 . V	Front Rear O
GIA / PR Seen:	WBal. mm R/Bal. mm
Est. Repairs:	/Bal mm L/Bal mm
Lum Sum: 20 % 3 Val: Yes or No	OA 23/11/22 D.O.I. 1/12/2027
3	urvey held at
CA / REV / REP. / 24 HRS	es. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Verlice: IN / OUT	OIS mean
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Est not ready	
1.51	
Date/Time, File Pass to?	
: Prell. Report Days	Of Repair:
	vey No. of Trip: Survey Fee
2)	
	Site Insp (\$
	Intendeur /t
report rounds.	1, 10.35
	Tech Invs (\$
	Weekend (\$
	TOTAL

SL0M22BS000F / Lai Huat (Meng Kee) Motor Pte Ltd ENTRY DATE & TIME: 28/11/2022 16:02 (SGT) SUBMITTED BY: Jenny Lim VERSION: 1 (28/11/2022 16:02 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
 2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Arry false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving
- and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCIDENT STATEMENT

Date of Submission Reported by

Date of Accident Exact Location of Accident

Additional Location Information

Country/State of Loss

28/11/2022 16:02 (SGT)

Driver

25/11/2022 21:15 (SGT)

Bukit Manis Rd, Singapore

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SKN1213S

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address

Mobile Phone No.

Alternative Phone No

Yes

Jurong Engineering Limited

200500869G

slng@jel.com.sg

(Phone) +65-66600357

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Transmission

CC

Mercedes

S350I

Private use

No - Claiming third party

Private car

Auto

2987

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

AIG Asia Pacific Insurance Pte. Ltd.

2100481673-06

DRIVER

Name of Driver

NRIC No

Date Of Birth

Occupation

Batumalai S/O Rajoo

S2645431Z

25/07/1953

Outdoor



Accident report SL0M22BS000F

