


ASS. REC. BY: Kenneth REF: ALS/22008259/KV

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
To inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s Spax  
of 1236  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: GBD 6960U Yr Regn: 03/15  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: NIS NV200 c.c. 1461  
Colour: White A/C: Insured / Std / NI / NA  
Sp. Reading: 98833 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: YSK YBAM 207 0082730  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Mod: Nil S/Rim / STD A/Rim or  
Tyre Size: Pirelli 175/70R14  
R: GY

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 229k  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 14 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_  
Front R/Bal. 6 mm Rear R/Bal. 93 mm  
L/Bal. 6 mm L/Bal. 9 mm  
D.O.A. 20/6/22 D.O.I. 30/5/2022

CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?  : Prell. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:	
Transportation:	
S - RS. SI	
Fees	
Others	
TOTAL	

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech Invs (\$)  
 : Weekend (\$)

Report Format :  
Lump Sum / I.B.I: (\$)



Vehicle & Motor Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TP

Vehicle No. : GBD6960U

Make & Model : NISSAN NV200 1.5L

Year of Manufacture : 2015

Chassis No. : VSKYBAM20Z0092730

Engine No. : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Time of Accident : \_\_\_\_\_

Ins Company : GE VS ALLIANZ

Excess : \_\_\_\_\_

Date of Accident : 20/06/2022

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor

Case Owner : PATRICK

Signature : \_\_\_\_\_

**Contact No  
Frt Counter Operation**

Brenda Tel: 63837730 email: brendang@sparkcarcare.com

Rohani tel: 63837890 email: rohanim@sparkcarcare.com

**Back-end Operation**

Ngo Toh Wee Tel: 63837656 email: ngotw@sparkcarcare.com

Patrick Tel: 63837441 email: patricktia@sparkcarcare.com

**Repair Estimates**

Parts (a) Cost / List Price Items \$ -

Plus/Less 10% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ **12,017.00**

Less 10% \$ **1,201.70**

Total of Nett Item \$ **10,815.30**

(c) Special Nett Items \$ **2,883.00**

**Total Parts Cost (Appendix A) \$ 13,698.30**

**Labour (Appendix B) \$ 7,700.00**

**Total Repair Cost \$ 21,398.30**

The above total will be subjected to 7% G.S.T.

*NOT Authorized  
U/Rng &  
Permy After Pain*

Name of Surveyor : Thenneth  
Company : LICK  
Survey conducted on : 30/6/22 at \_\_\_\_\_

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 10 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 30/6/22

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
 205 Braddell Road S (579701)  
 Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : GBD6960U Case Owner : PATRICK  
 Make & Model : NISSAN NV200 1.5L Year Manufac : 2015  
 Chassis No : VSKYBAM20Z0092730 Engine No : 0  
 Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
 Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR BUMPER	1		<i>By</i>	\$ 525.00		✓
2	REAR BUMPER RETAINER RH	1		<i>Dis</i>	\$ 41.00		✓
3	REAR BUMPER RETAINER LH	1		<i>CM</i>	\$ 41.00		✓
4	BUMPER SPONGE	1		<i>CM</i>	\$ 102.00		✓
5	BUMPER CLIP	8		<i>Ne</i>	\$ 40.00		✓
6	REVERSE SENSOR	2		<i>Short</i>		\$ 250.00	<i>2 Gdn</i>
7	REAR BUMPER REFLECTOR RH	1			\$ 67.00		?
8	REAR BUMPER REFLECTOR LH	1			\$ 67.00		?
9	REAR END PANEL OUTER	1		<i>By</i>	\$ 124.00		✓
10	REAR END PANEL INNER	1		<i>By</i>	\$ 622.00		✓
11	REAR END PANEL TOP GARNISH	1			\$ 124.00		?
12	REAR FLOOR CARPET	1			\$ 2,000.00		?
13	REAR RH BACK DOOR	1		<i>By</i>	\$ 984.00		✓
14	RR RH BACK DOOR GLASS	1		<i>Ln</i>	\$ 517.00		X
15	SEALANT	1			<i>Ne</i> \$ 40.00		✓
16	REAR 5PAX STICKER	1			<i>Ne</i> \$ 30.00		<i>155N</i>
17	REAR 70KM/H STICKER	1			<i>Ne</i> \$ 18.00		<i>155N</i>
18	RR RH BACK DOOR VERTICAL RUBBER SEAL	1		<i>Dis/ln</i>	\$ 65.00	✓	✓
19	RR RH BACK DOOR LOCK TOP	1			\$ 107.00		?
20	RR RH BACK DOOR LOCK LOWER	1			\$ 125.00		?
21	RR RH BACK DOOR LOCK LOWER CATCH	1			\$ 38.00		?
22	RR RH BACK DOOR HINGE TOP	1			\$ 105.00		?
23	RR RH BACK DOOR HINGE LOWER	1			\$ 116.00		?
24	RR RH BACK DOOR INNER TRIM BOARD	1		<i>Sen</i>	\$ 130.00		X
25	RR LH BACK DOOR	1		<i>By</i>	\$ 1,312.00		✓
26	RR LH BACK DOOR HINGE TOP	1			\$ 116.00		?
27	RR LH BACK DOOR HINGE LOWER	1			\$ 116.00		?
28	RR LH BACK DOOR LOWER LOCK CATCH	1		<i>Tn</i>	\$ 38.00		✓
29	RR LH BACK DOOR INNER TRIMBOARD	1		<i>Return</i>	\$ 130.00		✓
30	RR LH SIDE PANEL OUTER	1		<i>By</i>	\$ 1,767.00		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spares Parts

Vehicle No : GBD6960U  
 Make & Model : NISSAN NV200 1.5L  
 Chassis No : VSKYBAM20Z0092730  
 Sales Order : 0  
 Order By : 0

Case Owner : PATRICK  
 Year Manufac : 2015  
 Engine No : 0  
 Supplier : 0  
 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	RR LH SIDE PANEL INNER	1			\$ 1,463.000		?
32	RR LH SIDE PANEL AIR VENT	1			\$ 75.000		?
33	LH TAILLAMP	1		<i>B/O</i>	\$ 340.000		✓
34	RH TAILLAMP	1		<i>CM</i>	\$ 340.000		✓
35	LH BACK DOOR NUMBER PLATE GARNISH	1			\$ 380.000		?
36	RR NUMBER PLATE W/CASE/LONG/EMBOSS / BLACK NO.	1			<i>R1</i> \$ 45.00		✓
37	0	1				\$ -2,500.00	
38	0	1					
39	0	1					
40	0	1					
41	0	1					
42	0	1					
43	0	1					
44	0	1					
45	0	1					
46	0	1					
47	0	2					
48	0	1					
49	0	5					
50	0	1					
51	0	5					
52	0	1					
53	0	1					
54	0	1					
55	0	1					
56	0	1					
57	0	1					
58	0	1					
59	0	1					
60	0	1					

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge be charged accordingly under supplementary.*



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 21/06/2022 09:31 (SGT)  
Date of Accident ..... 20/06/2022 13:30 (SGT)  
Exact Location of Accident ..... Near 157A Tamarind Rd, Singapore 806105  
Regional Location Information ..... SLE TOWARDS CTE  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... GBD6960U

### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... NCS COMMUNICATIONS ENGINEERING PTE. LTD.  
Company Reg No ..... 1XXXXX123G  
Email Address ..... tahn@ncs.com.sg  
Mobile Phone No ..... (Phone) +65-65420573  
Alternative Phone No ..... +65-65420573

### VEHICLE PARTICULARS

Manufacturer ..... Nissan  
Model ..... Nv200  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Employment  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Commercial vehicle  
Transmission ..... Manual  
CC ..... 1600

### INSURANCE COMPANY

Name of Insurance Company ..... Great Eastern General Insurance Limited  
Type of Coverage ..... ThirdParty  
Fleet Policy ..... Yes  
Policy Number ..... -  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... NG BUCK SOON  
NRIC No ..... SXXXX221B

**IMPORTANT NOTICE**

**SKETCH PLAN**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

\* Note trying to avoid front accident,

