

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

mileage: 619925

Vehicle No. : SHA2746T
 Make : HYUNDAI
 Model : IONIQ(G3)

Date: 24.11.2022
 Insurance: CHINA TAIPING
 MVA: MS. LOKE YY

| Qty | Parts Description / Labour | Type | Unit Price | Amount |
|-----|--|------|------------|------------|
| 1 | REAR BUMPER COVER / cut cut | | | \$459.40 |
| 10 | REAR BUMPER CLIPS / NCL | | | \$22.00 |
| 1 | REAR BUMPER CENTRE MOULDING ASSY ?XIVN | | | \$451.25 |
| 1 | REAR BUMPER REINFORCEMENT R | | | \$394.80 |
| | | | | |
| | | | 481 | \$1,327.45 |
| | | | 96 | \$265.49 |
| | | | 385 | \$1,061.96 |
| | | | | |
| | REAR BUMPER RUBBER MAT NCL | | | \$50.00 |
| | REAR BUMPER REVERSE SENSOR mm? NN | | | \$180.00 |
| | | | 50 | \$230.00 |
| | | | | |
| | Labour Charge | | | |
| | PANEL BEATING | | 350 | \$400.00 |
| | SPRAY PAINTING CHARGE | | 250 | \$300.00 |
| | REMOVE/REFIX REVERSE SENSOR | | 30 | \$80.00 |
| | | | 630 | \$780.00 |
| | | | | |
| | | | 1065 | \$2,071.96 |
| | | | 20% = 213 | |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Final T = 852

11am 90097659
 24/11/22 3pm
 3 days. ≈ 850
 L/S After paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: