NCVI INVOLVING STAFF CAR MID28 AND CIVILIAN VEHICLE SKR838A ALONG PIE TOWARDS CHANGI BEFORE EXIT 24 TO BKE ON 30 NOV 22 AT AROUND 1900HRS




Figure 1A: Schematic Diagram




Figure 1B: Schematic Diagram




Figure 1C: Schematic Diagram




Figure 1D: Schematic Diagram




Figure 1E: Schematic Diagram

$OFFICIAL\ (CLOSED) \setminus SENSITIVE\ NORMAL$




Figure 1F: Schematic Diagram



Figure 2A: Front View of MID 28




Figure 2B: Rear View of MID 28



Figure 2c: Side View of MID 28



Figure 2D:Side View of MID 28




Figure 2E: Front View of MID28 at Incident Location




Figure 2F: Contact between SKR838A and MID28



Figure 2G: Contact between SKR838A and MID28



Figure 2H: Front View of SKR838A




Figure 2I: Rear view of SMD5130A in front of MID28 (final position)





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 1 of 3 Report No. T/20221130/7078

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/11/2022 22:18			Vide Report No.:	Station Diary No.:			
Informant's Particulars							
Name of Informant:			Address:				
PANG LEAD SHUAN							
ID Type / ID No.: NRIC NO / S 629I			Contact No.: Home/Office:	Mobile:			
Nationality:			Email:				
SINGAPORE CITIZEN							
Sex:	Age:	Date of Birth:	Type of Informant:				
Male	43	12/02/1979	Driver				
Race:			Language:	Institution / School Name:			
Chinese			English				
Occupation: Army Officer			Driving Licence Information: Class:	Date of Ex	piry:		

General Information of the Accident							
Type of Accident:	Non-Injury Others	Drink Drive No	:	Date/Time of Accident: 30/11/2022 19:00)	Type of Location: Straight Road	
Location:	•						
PIE							
Mosther		Road Surface			Door	d Coood Limit	
Weather: Drizzling			ð.		70 K	d Speed Limit: m/h	
Traffic Flow: One Way		Traffic Controlle				Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear					Anyone conveyed by ambulance: No		

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Conditio	No of
SKR838A	Car	HONDA				0
SMD5130A	Car	BMW				0
SNE8417L	Car					0

Figure 3A: Police Report Part 1





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 3 Report No. T/20221130/7078

CONTINUATION OF REPORT

Details of Person Involved								
Any Pedestrian Involved: No								
No. of Pedestrian		Use of Pedestrian Crossing: NA						
Driver	·							
Name	TAN JIONG QUAN B		ID No.		S 372D			
Related Vehicle	SKR838A (Car)			Contact No.				
Hospital/Clinic	NIL			Class of Driving Licence & Expiry		Class: NIL Date of Expiry: NIL		
Date	NIL		Date	NIL				
No. of Days granted Medical Leave NIL			Degree of		NIL			
Driver								
Name	PANG LEAD SHUAN			ID No.		S 629I		
Related Vehicle	SNE8417L (Car)			Contact No.				
Hospital/Clinic	NIL			Class of Driving Licence & Expiry		Class: NIL Date of Expiry: NIL		
Date	NIL	Date	NIL					
No. of Days granted Medical Leave NIL			Degree of NIL					

Brief Details.

i was travelling along PIE towards Changi, just before the BKE exit, when the car in front of me braked and hit the car in front of it. I am immediately applied my brake hard and managed to stop in time, without hitting the car infront. Thereafter, the car behind me hit my car's rear. I have taken photos of the cars in front and behind me after the accident.

Figure 3B: Police Report Part 2





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20221130/7078

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 30/11/2022 22:18
Officer In Charge Of Case: TP / TPIB / MUHAMMAD NOOR BIN ABDUL RAHMAN Contact No.: 65476219	Classification Of Case:
NP168	

Figure 3C: Police Report Part 3