



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS3/SMO22007353/Eqy3e2-1 Date: 07/12/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLN 8749E	Veh. Inspected	SNE 9985G
Policy No.	D22MTPV01006434	Coverage (\$)	0.00
Claim No.	CMTD2202608/SYH	Excess (\$)	0.00
Assign From	HWANG SHIANG YI	Assign Date	15/11/2022
2. Vehicle Particulars & Condition			
Make & Model	RENAULT MEGANE	c.c	1618
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VF1RFB00655649392	Colour	BLUE
Odometer	105949 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/50 R17	MICHELIN	4 mm
L/H Front Tyre	215/50 R17	MICHELIN	4 mm
R/H Rear Tyre	215/50 R17	MICHELIN	4 mm
L/H Rear Tyre	215/50 R17	MICHELIN	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/07/2022	Inspection Date	02/08/2022
Survey held at	No 1 Bukit Batok Crescent, 02-20 Wcega Plaza		
Repairer	GARAGE STAR PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	