

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / T / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SNB 3995H
 at Workshop no/s WEARMS AUTOMOTIVE
 of MURAMBURA RD
 Insured: AD
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 174K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SNB 3995H Yr Regn: 2021 / BUH
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
 Make: VOLVO XC40T4R-DEWH cc 1969
 Colour: GREY A/C: Insured / Std / NI / NA
 Sp. Reading: 20833 T/Radio: Insured / Std / NI / NA
 Eng No: _____
 C/No: LYVXZAKADML585091
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: NR / SRim / STD ARim or
 Tyre Size: F: 235/50R19
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 30/11/22 D.O.I. 13/12/22
 Survey held at WEARMS
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
o/s FRt
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
REPAIR LIMIT - 97K

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) _____
 Date/Time, File Return to?

2) _____
 Report Format : _____
 Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: _____
 Transportation: _____
 S + RS: _____
 Photos: _____
 Other: _____
 TOTAL: _____

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Wong Kwok Kwong
10 Old Upper Thomson Road
#02-06

Singapore 573869

GST Reg.No: M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 01/12/2022
WIP No. . : 52668
Veh.In/Out:

*Tel.No. . : Mobile: 83999159
Reg.No. . : SNB3995H
Reg.date . : 19/08/2021
Mileage .. : 0
Chassis No: LYVXZAKADML585891

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Wong Kwok Kwong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER, FRONT LOWER BUMPER, RHF FENDER WIDENER, BRACKETS, CLIPS, ETC.	0	1700.00	0	1,700.00	S	850
800	TO BLEND AND SPRAY PAINT ON FRONT BUMPER, ETC.	0	1500.00	0	1,500.00	S	750
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	588.00	0	588.00	S	
	VO39790879/BUMPER CO	1.0 EA	2309.70			2,309.70	S
	BUMPER SPOILER FRT A	1.0 EA	590.40			590.40	S
	WHEEL AIR DEFLECTOR	1.0 EA	81.20			81.20	S
	WIDENER FRT RH XC40	1.0 EA	202.90			202.90	S
	BUMPER INSTALLING MT	1.0 EA	101.40			101.40	S
	BUMPER CLIP XC90 16-	10.0 EA	8.80			88.00	S
	BLIND RIVET 4.0*21 P	10.0 EA	5.00			50.00	S
	BUMPER CLIP 8x8,5	10.0 EA	8.20			82.00	S
	BUMPER CLIP GREEN S6	10.0 EA	6.00			60.00	S

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Wong Kwok Kwong
10 Old Upper Thomson Road
#02-06

Singapore 573869

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Wong Kwok Kwong

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 01/12/2022
WIP No. . : 52668
Veh.In/Out:
*Tel.No. . : Mobile: 83999159
Reg.No. . : SNB3995H
Reg.date . : 19/08/2021
Mileage .. : 0
Chassis No: LYVXZAKADML585891

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	EXPANDING NUT XC40 1 <i>Be</i>	10.0 EA	6.70			67.00	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasa
Hp 9000068
3 days
13/12/22 @ 1130
Resurvey before print

	Gross Total.	7,420.60
Labour Total	3,788.00	Net..... 7,420.60
Parts Total	3,632.60	GST @ 7.0% 519.44
Package Total	0.00	Total..... 7,940.05
		Paid..... 0.00
		Please Pay.. 7,940.05

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 30/11/2022 17:46 (SGT)
Reported by Both
Date of Accident 30/11/2022 12:39 (SGT)
Exact Location of Accident Singapore
Additional Location Information 6 SIN MING ROAD (CARPARK)
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SNB3995H

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner WONG KWOK KWONG
NRIC No SXXXX170B
Email Address aliciawmng@gmail.com
Mobile Phone No (Phone) +65-96537183
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Volvo
Model Xc40
Variant XC40 T4
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1969

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number 7210096095

DRIVER

Name of Driver ALICIA NG WENG MING
NRIC No SXXXX171J
Date Of Birth 19/10/1975
Occupation Indoor

Driving experience	09/06/2018
Gender	4 YEARS AND 5 MONTHS
Mobile Number	Female
Alt. Phone Number	(Phone) +65-96537183
Email Address	-
Address	aliciawmng@gmail.com
Address complement	10 OLD UPPER THOMSON ROAD
Postcode	#02-06
Is the driver the policyholder?	573869
If No, Relationship of the Driver with the Insured	No
Does Driver Own Other Vehicles?	Spouse
Vehicle Registration Number of Other Vehicle Owned by Driver	No
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMJ4834C
Vehicle Manufacturer	Honda
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	Black
Vehicle Category	Private car
Name of Driver	LEE ZHI PING
	SXXXX524B

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for Investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstance of the Accident

I drove into the carpark on 6 Sin Ming Road to take my kids to AEROV optician. Whilst parked in a proper parking lot and waiting (with plenty of parking lots available next to me), grab car SMJ4834C reversed trying to park in the lot next to where I was parked. He reversed (whilst using his mobile phone which he admitted as he was picking up a customer's call) and did not realise my car was parked and knocked into my bumper. I honked when I realised he knocked and he stopped. He came out and apologised saying he was on mobile and did not see my car next to his. He admitted that it was his mistake and asked me to claim against his insurance.

IMPORTANT NOTE

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 170B

Vehicle Details

Vehicle No.: SNB3995H

Vehicle to be Exported: No

Intended Deregistration Date: 13 Dec 2022

Vehicle Make: VOLVO

Vehicle Model: XC40 T4 R-DESIGN

Primary Colour: Silver

Manufacturing Year: 2021

Engine No.: B4204T317700741

Chassis No.: LYVXZAKADML585891

Maximum Power Output: 140.0 kW (187 bhp)

Open Market Value: \$28,316.00

Original Registration Date: 19 Aug 2021

First Registration Date: 19 Aug 2021

Transfer Count: 0

Actual ARF Paid: \$31,643.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Aug 2031

PARF Rebate Amount: \$23,732.00

Intended COE Rebate Details

COE Expiry Date: 18 Aug 2031

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$61,001.00

COE Rebate Amount: \$52,949.00

Total Rebate Amount: \$76,681.00

Volvo XC40 T4 R-Design

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$172,500

Depreciation 

\$18,180 /yr
[View models with similar depre](#)

Reg Date

26-Jul-2021
(8yrs 7mths 12days COE left)

Mileage

15,000 km (10.8k /yr)

Manufactured 

2021

Road Tax

\$1,176 /yr

Transmission

Auto

Dereg Value 

\$69,664 as of today ([change](#))

OMV 

\$28,316

COE 

\$62,000

ARF

\$31,643

Engine Cap

1,969 cc

Power

140.0 kW (187 bhp)

Curb Weight 

1,695 kg

No. of Owners

2

Type of Vehicle

SUV