

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22012107/Rvp3m4	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811			Date:	09/12/2022	
	ATTN: LOH CYNTH	AIA		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 4729E	Veh. Inspected	l	GBA 7108Z	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M04FR6	Excess (\$)		0.00	
	Assign From	LOH CYNTHIA	Assign Date		02/12/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HILUX DOUBLE CAB	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2007	
	Chassis No.	MR0EZ12GX04150767	Colour		GREY	
	Odometer	310292 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/65 R16	GOODYEAR		7 mm	
	L/H Front Tyre	215/65 R16	GOODYEAR		7 mm	
	R/H Rear Tyre	215/65 R16	GOODYEAR		7 mm	
	L/H Rear Tyre	215/65 R16	GOODYEAR		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT AND O/S FRONT PORTION.					
5.	General Information					
	Accident Date	30/11/2022	Inspect Date /	Time	05/12/2022 ( 04:36 PM )	
	Survey held at	rey held at 5 SOON LEE STREET #06-36 PIONEER POINT (S) 627607				
	Repairer	Repairer TAI TIONG AUTO MOBIL TRADING				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				
			ON 40004 04 07/D			

Report Ref No. CS3/ASM22012107/Rvp3m4

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser