

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 87693at Workshop m/s BORNCO MOTORof 2, DORMAN CRESCENTInsured: SHF 185Z SNIL

Policy No. _____


Claims No. TAX/11/22/2059

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 56K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLH 87693Yr Regn: 2016 1 OCTType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA ALTI 1.6 c.c. 1598Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 468201 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053RKH104558000Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55 R16

R: _____

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 30/11/22D.O.I. 05/12/22Survey held at BORNCO MOTORDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIA II - 25K

22/12/22 Final fig \$22,891.20 confirmed by email (Red 5534.80, 19%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 22/12/22-typist

Days Of Repair: 8

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Report Format: TP

Lump Sum / I.B.I: (\$ 22,891.20)

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS SI

) Photos

) Others



b. Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
b. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

on behalf of	Customer's Signature	Charge Summary	Total
Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	Less
		Lubrication/Fluid	
		Others	
			Amount Due



Borneo Motors



TOYOTA

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 01/12/2022	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGKZ Q3	17/10/2016	SLG8769J	0	18890	66TP/SLG8769J/301122

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR053REH104558000	1ZRY332131	60	Shashitharan	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
16	6	K67002-02470 PANEL SUB-ASSY, FR D	1.00	1495.20		1495.20
17	7	K75922-02220 TAPE, BLACK OUT, NO.	1.00	57.20		57.20
18	8	K75924-02250 TAPE, BLACK OUT, NO.	1.00	51.90		51.90
19	9	K67004-02430 PANEL SUB-ASSY, RR D	1.00	1481.90		1481.90
20	0	K75444-02A20 PLATE, LUGGAGE COMPT	1.00	42.30		42.30
21	1	K42450-02211 HUB & BRG ASSY, RR A	1.00	1143.90		1143.90
22	2	K42611-02C80 WHEEL, DISC	2.00	2390.80		4781.60
23	3	S43420-02A10 SHAFT ASSY, FR DRIVE	1.00	1486.20		1486.20
24	4	K90080-36137 BEARING, RADIAL BALL	1.00	129.10		129.10
25	5	K43502-02110 HUB SUB-ASSY, FR AXL	1.00	311.40		311.40
26	6	K43330-09681 JOINT ASSY, LWR BALL	1.00	283.60		283.60
27	7	K43212-02270 KNUCKLE, STEERING, L	1.00	747.30		747.30
28	8	K48069-02260 ARM SUB-ASSY, SUSPEN	1.00	873.80		873.80
29	9	K48520-8Z056 ABSORBER SET, SHOCK,	1.00	523.40		523.40

*Same
4p 20010068
8 days
05/12/22 @ 1410
Resy before paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts replaced subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer's Signature

Charge Summary

Total

27,201.30

Parts	16,865.30
Labour	10,176.00
Sublet	160.00
Lubrication/Fluid	0.00
Others	0.00

GST 7.00%

1,904.09

Less

0.00

Amount Due

29,105.39

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	200G
Vehicle No.:	SLG8769J
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Dec 2022
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZRY332131
Chassis No.:	MR053REH104558000
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$16,800.00
Original Registration Date:	17 Oct 2016
First Registration Date:	17 Oct 2016
Transfer Count:	2
Actual ARF Paid:	\$16,800.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Oct 2026
PARF Rebate Amount:	\$10,920.00
COE Expiry Date:	16 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,000.00
COE Rebate Amount:	\$19,287.00
Total Rebate Amount:	\$30,207.00

The Information contained herein is correct as at 07 Dec 2022

OK