



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KHOR SAW THENG			Ref: CS3/ASM22003306/Tvp3e2-1 Date: 04/01/2023 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 8503X	Veh. Inspected	SMT 2880D
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M03Y6G	Excess (\$)	0.00
	Assign From	KHOR SAW THENG	Assign Date	02/12/2022
2. Vehicle Particulars & Condition				
	Make & Model	KIA CERATO	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	KNAF3416ML5070236	Colour	GREY
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	MICHELIN	6 mm
	L/H Front Tyre	205/55 R16	MICHELIN	6 mm
	R/H Rear Tyre	205/55 R16	MICHELIN	6 mm
	L/H Rear Tyre	205/55 R16	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	09/04/2022	Inspection Date	13/12/2022
	Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	