



Service Request Details

Claim

S2M03Y6G

Reference

CS3/ASM22003306/p3-1

Loss Date

9 April 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

11 Apr 2022 12:15:02 PM

Request Date

2 December 2022

Due Date

2 December 2023

Services

Re-inspection

Actions

Next Step

Finish the work

Complete Work

Vehicle Information

Incident Vehicle Registration #
SMT2880D

Make
TPVD Hyundai

Model
I40

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

KHOR Saw Theng

sawtheng.khor@axa.com.sg

Additional Instructions
Please conduct re-inspection and send us report.

Messages1

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SUBJECT

Assignment

BODY

Dear Saw Theng, Thank you for the assignment.

