



Letter of Claims
Request of direct settlement.

Volkswagen Group Singapore Pte Ltd

We are submitting a claim on behalf of our customer _____

NRIC 1991014047 insured of vehicle SMF58735 against

your insured vehicle number SMR3468P (Loupac)

On the accident dated on 01/12/2020 (ddmmyyy) along

Along the AKE about 40 exit onto Mandai Ave

Dated this 01 (day) of 12 (month) 20 20.



Volkswagen Group Singapore

247 Alexandra Road

Singapore 159934

DID: 6305 7216

HP: 81214681

meiy.wong@vw.com.sg

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial Vehicles

Quotation

Non binding - Preview

Page 1/2

Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

Customer Details:
Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

Document no.
Document date 02-12-2022
Customer no. 5211043801
Customer GST-ID
Dealer 30001
Job order number 2022035308/ 1
Job order date 02-12-2022
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SNF5873S	C113KZR1	07-06-2022	WVGZZC1ZNY079015	T-Cross R-Line 1.0 I TSI 85kW DSG	18

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
2GM807421 GRU	Cover For Bumper Primed REAR BUMPER (UPPER)	1	pcs.	1,280.79	#1	1,280.79	1,370.45
2GM919397 GRU	Sensor Bracket Primed	1	pcs.	14.79	#1	14.79	15.83
2GM919398 GRU	Sensor Bracket Primed	1	pcs.	14.79	#1	14.79	15.83
2GM919491	Sensor Bracket	1	pcs.	12.92	#1	12.92	13.82
2GM919492	Sensor Bracket	1	pcs.	12.92	#1	12.92	13.82
2GM919491A	Sensor Bracket	2	pcs.	12.92	#1	25.84	27.65
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	#1	68.85	73.67
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	#1	85.94	91.96
2GM807521B GRU	Spoiler Primed REAR BUMPER (CTR)	1	pcs.	320.09	#1	320.09	342.50
2GM807568A 9B9	Rear Diffusor Satin Black REAR BUMPER (LOWER)	1	pcs.	249.00	#1	249.00	266.43
2GM807305	Bumper Bracket REINFORCEMENT	1	pcs.	709.97	#1	709.97	759.67
2GM807863A	Attachment Strip BUMPER CTR BRACKET	1	pcs.	70.05	#1	70.05	74.95
2GM807393P	Guide Piece LHR BUMPER BRACKET (UPPER)	1	pcs.	42.59	#1	42.59	45.57
2GM807394P	Guide Piece RHR BUMPER BRACKET (UPPER)	1	pcs.	42.59	#1	42.59	45.57
2GM807393M	Guide Piece LHR BUMPER BRACKET (SIDE)	1	pcs.	40.20	#1	40.20	43.01
2GM807394M	Guide Piece RHR BUMPER BRACKET (SIDE)	1	pcs.	40.20	#1	40.20	43.01
2GM945701A	Reflector LH	1	pcs.	81.02	#1	81.02	86.69
	LABOUR	3	pcs.	840.00	#1	2,520.00	2,696.40
	SPRAY PAINT	4	pcs.	840.00	#1	3,360.00	3,595.20
	MSIG VS LONPAC 3RD PARTY VEHICLE SMR3968P D.O.A: 01-12-2022 SURVEY BY:						

Quotation valid till 09-12-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	8,992.55	7%	682.68	9,752.55	10,435.23
Total	760.00	8,992.55		682.68	9,752.55	10,435.23

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Commercial
Vehicles

Quotation

Non binding - Preview

Page 2/2

Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

Customer Details:
Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

Document no.
Document date 02-12-2022
Customer no. 5211043801
Customer GST-ID
Dealer 30001
Job order number 2022035308/ 1
Job order date 02-12-2022
Service Advisor YEN MEI WONG

License plate SNF5873S	Model code C113KZR1	First registration 07-06-2022	VIN WVGZZZC1ZNY079015	Model T-Cross R-Line 1.0 I TSI 85kW DSG	Mileage 18
---------------------------	------------------------	----------------------------------	--------------------------	--	---------------

Customer



-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

All invoices are denominated in SGD, unless otherwise stated.