

(08/11/23) wof

ASS. REC. BY: Jan

REF:

CC4/LPC 22 012126/Rpa3

4942

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / T / P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNF 58735at Workshop n/s VOLKSWAGENof 247, ALEXANDER RDInsured: LPC

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

3.30pm

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 140K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 54K

Veh No: SNF 58735 Yr Regn: 2022 7 JunType: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLKSWAGEN T-CROSS RL cc 999Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 3558 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVG 222C1ZNY071015

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NI / SRim / STD A/Rim orTyre Size: F: 205/55R17R: nBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mmL/Bal: 6 mm L/Bal: 6 mmD.O.A. 01/12/22 D.O.I. 07/12/22Survey held at VOLKSWAGENDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

) S + RS _____ SI

☐ : Interview (\$ _____)

) Photos

☐ : Tech. Invs (\$ _____)

) Others

☐ : Weekend (\$ _____)

) TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____)

TOTAL

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/2

Document no.
Document date 02-12-2022
Customer no. 5211043801
Customer GST-ID
Dealer 30001
Job order number 2022035308/ 1
Job order date 02-12-2022
Service Advisor YEN MEI WONG

Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

Customer Details:
Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

License plate	Model code	First registration	VIN	Model	Mileage
SNF5873S	C113KZR1	07-06-2022	WVGZZC1ZNY079015	T-Cross R-Line 1.0 I TSI 85kW DSG	18

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
2GM807421 GRU	Cover For Bumper Primed REAR BUMPER (UPPER)	1	pcs.	1,280.79	#1	1,280.79	1,370.45
2GM919397 GRU	Sensor Bracket Primed	1	pcs.	14.79	#1	14.79	15.83
2GM919398 GRU	Sensor Bracket Primed	1	pcs.	14.79	#1	14.79	15.83
2GM919491	Sensor Bracket	1	pcs.	12.92	#1	12.92	13.82
2GM919492	Sensor Bracket	1	pcs.	12.92	#1	12.92	13.82
2GM919491A	Sensor Bracket	2	pcs.	12.92	#1	25.84	27.65
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	#1	68.85	73.67
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	#1	85.94	91.96
2GM807521B GRU	Spoiler Primed REAR BUMPER (CTR)	1	pcs.	320.09	#1	320.09	342.50
2GM807568A 9B9	Rear Diffusor Satin Black REAR BUMPER (LOWER)	1	pcs.	249.00	#1	249.00	266.43
2GM807305	Bumper Bracket REINFORCEMENT	1	pcs.	709.97	#1	709.97	759.67
2GM807863A	Attachment Strip BUMPER CTR BRACKET	1	pcs.	70.05	#1	70.05	74.95
2GM807393P	Guide Piece LHR BUMPER BRACKET (UPPER)	1	pcs.	42.59	#1	42.59	45.57
2GM807394P	Guide Piece RHR BUMPER BRACKET (UPPER)	1	pcs.	42.59	#1	42.59	45.57
2GM807393M	Guide Piece LHR BUMPER BRACKET (SIDE)	1	pcs.	40.20	#1	40.20	43.01
2GM807394M	Guide Piece RHR BUMPER BRACKET (SIDE)	1	pcs.	40.20	#1	40.20	43.01
2GM945701A	Reflector LH	1	pcs.	81.02	#1	81.02	86.69
	LABOUR	2	pcs.	840.00	#1	2,520.00	2,696.40
	SPRAY PAINT	1	pcs.	840.00	#1	3,360.00	3,595.20
	MSIG VS LONPAC						
	3RD PARTY VEHICLE SMR3968P						
	D.O.A: 01-12-2022						
	SURVEY BY:						

Quotation valid till 09-12-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	8,992.55	7%	682.68	9,752.55	10,435.23
Total	760.00	8,992.55		682.68	9,752.55	10,435.23

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

Customer Details:
Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

Document no.
Document date 02-12-2022
Customer no. 5211043801
Customer GST-ID
Dealer 30001
Job order number 2022035308/ 1
Job order date 02-12-2022
Service Advisor YEN MEI WONG

License plate SNF5873S	Model code C113KZR1	First registration 07-06-2022	VIN WVGZZC1ZNY079015	Model T-Cross R-Line 1.0 I TSI 85kW DSG	Mileage 18
---------------------------	------------------------	----------------------------------	-------------------------	--	---------------

Customer



—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rene
Hp 90010068
3 days
07/12/22 P1550
Rene before paint

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

494Z

Vehicle Details

Vehicle No.:

SNF5873S

Vehicle to be Exported:

No

Intended Deregistration Date:

08 Dec 2022

Vehicle Make:

VOLKSWAGEN

Vehicle Model:

T-CROSS R-LINE

Primary Colour:

Grey

Manufacturing Year:

2022

Engine No.:

DKJ124524

Chassis No.:

WVGZZZC1ZNY079015

Maximum Power Output:

85.0 kW (113 bhp)

Open Market Value:

\$22,345.00

Original Registration Date:

07 Jun 2022

First Registration Date:

07 Jun 2022

Transfer Count:

0

Actual ARF Paid:

\$23,283.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

06 Jun 2032

PARF Rebate Amount:

\$17,462.00

Intended COE Rebate Details

COE Expiry Date:

06 Jun 2032

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$71,556.00

COE Rebate Amount:

\$67,943.00

Total Rebate Amount:

\$85,405.00

Volkswagen T-Cross 1.0A TSI R-Line

Overview

Financial

Accessories

Similar

Research

Photos

Map

Das WeltAuto.

Used cars you can trust. Guaranteed.

Price **\$142,988**

Depreciation  \$13,590 /yr
[View models with similar depre](#)

Reg Date 05-Aug-2022
(9yrs 7mths 27days COE left)

Mileage 2,500 km

Manufactured  2022

Road Tax  \$392 /yr

Transmission Auto

Dereg Value  \$86,644 as of today ([change](#))

OMV  \$22,380

COE  \$71,556

ARF  \$23,332

Engine Cap 999 cc

Power 85.0 kW (113 bhp)

Curb Weight 1,369 kg

No. of Owners 1