



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref: CS/GAI22012149/Kwy3m4

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date: 13/01/2023

Code: GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMS 6136Z	Veh. Inspected	SML 7843X
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000001275	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	05/12/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT (A)	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GK31351218	Colour	METALLIC GREY
Odometer	72194 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60R15	MICHELIN	8 mm
L/H Front Tyre	185/60R15	MICHELIN	8 mm
R/H Rear Tyre	185/60R15	MICHELIN	8 mm
L/H Rear Tyre	185/60R15	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/11/2022	Inspection Date	06/12/2022
Survey held at	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------