

ASS. REC. BY:

REF:

GAZ/ 22012149/kw

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Yes

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNL 7843X Yr Regn: 06, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit

c.c.

1317

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

72194

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GK3

1351218

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

S

mm

Rear

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

29/11/22

D.O.I.

6/12/2022

Survey held at

Des. of Damages: Rear / O/S / N/S / UIC / Rooftop or

171 O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/12/22 8:44001 CASH 11/1/23 @ 05 days (Red \$16,153.60/79%)

Date/Time, File Pass to?

12/01/2023

1) Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair: 05

Resurvey No. of Trlp:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

: Fines

: Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$ L/S



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : GREAT AMERICAN INSURANCE COMPANY

3 TEMASEK AVE
SINGAPORE 039190

TEL: 6804 6000

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 29/11/2022

TP Veh Reg No: SMS6136Z

Estimate No: ES2200091

Date: 05 Dec 2022

Policy No:

Veh Reg No: SML7843X

Make/Model: HONDA FIT 1.3GF CVT

Chassis No: GK31351218

Engine No: L13B1461265

Reg. Date: 03/06/2019

*Not Notified
61 Day 84400h
Recovery After Repair
5 days*

Estimate Repair Cost to Vehicle No :SML7843X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 FRONT NUMBER PLATE	60.00	1 PC	CM 60.00	45.00
			60.00	60.00
Spare Parts				
2 AIR CON CONDENSER FAN MOTOR ASSY	859.80	1 SET	Sn 859.80	X
3 AIR-CON LIQUID PIPE	380.00	1 PC	Sn 380.00	X
4 AIR CON FAN COWLING	198.20	1 PC	Sn 198.20	X
5 AIRCON CONDENSER 810	950.80	1 PC	Sn 950.80	X
6 FRONT BONNET 712	1,112.40	1 PC	Sn 1,112.40	X
7 FRONT BONNET HINGE - LH	88.50	1 PC	DTI 88.50	X
8 FRONT BONNET HINGE - RH	88.50	1 PC	DTI 88.50	X
9 FRONT BONNET INNER RUBBER - LH	44.30	1 PC	Sn 44.30	X
10 FRONT BONNET INNER RUBBER CENTRAL - LH	49.40	1 PC	Sn 49.40	X
11 FRONT BONNET INSULATOR	192.40	1 PC	Sn 192.40	X
12 FRONT BONNET INSULATOR CLIPS	50.00	1 SET	Sn 50.00	X
13 FRONT BONNET LOCK	187.70	1 PC	Sn 187.70	X
14 FRONT BOONET INNER RUBBER - RH	44.30	1 PC	Sn 44.30	X
15 FRONT BUMPER 525	1,227.70	1 PC	CM 1,227.70	X
16 FRONT BUMPER AIR GRILLE CENTRAL	177.50	1 PC	Sn 177.50	X
17 FRONT BUMPER BRACKET - LH	64.30	1 PC	Sn 64.30	X
18 FRONT BUMPER BRACKET - RH	64.30	1 PC	DTI 64.30	X
19 FRONT BUMPER CLIPS	60.00	1 SET	Sn 60.00	X
20 FRONT BUMPER FOG LAMP - LH	527.40	1 PC	Sn 527.40	X
21 FRONT BUMPER FOG LAMP - RH	527.40	1 PC	Sn 527.40	X
22 FRONT BUMPER FOG LAMP BRACKET - LH	99.40	1 PC	Sn 99.40	X
23 FRONT BUMPER FOG LAMP BRACKET - RH	99.40	1 PC	Sn 99.40	X
24 FRONT BUMPER FOG LAMP COVER - LH	98.30	1 PC	Sn 98.30	X
25 FRONT BUMPER FOG LAMP COVER - RH 52.30	98.30	1 PC	DTI 98.30	X
26 FRONT BUMPER REINFORCEMENT 296.40	521.40	1 PC	Sn 521.40	X
27 FRONT BUMPER SIDE RETAINER - LH	52.60	1 PC	Sn 52.60	X
28 FRONT BUMPER SIDE RETAINER - RH	52.60	1 PC	DTI 52.60	X
29 FRONT BUMPER TOWING COVER	40.10	1 PC	Sn 40.10	X
30 FRONT FENDER - LH	780.40	1 PC	Sn 780.40	X
31 FRONT FENDER - RH	780.40	1 PC	Sn 780.40	X
32 FRONT FENDER SIDE GARNISH - RH	283.20	1 PC	Sn 283.20	X
33 FRONT GRILLE OUTER	265.50	1 PC	Sn 265.50	X
34 FRONT GRILLE CHROME MOULDING - LH	138.50	1 PC	Sn 138.50	X
35 FRONT GRILLE CHROME MOULDING - RH	138.50	1 PC	DTI 138.50	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE
SINGAPORE 039190

TEL: 6804 6000
ATTN: Motor Claim Department
Your Ref No: -
Claim Type: Third Party
Accident Date: 29/11/2022
TP Veh Reg No: SMS6136Z

Estimate No: ES2200091
Date: 05 Dec 2022
Policy No:
Veh Reg No: SML7843X
Make/Model: HONDA FIT 1.3GF CVT
Chassis No: GK31351218
Engine No: L13B1461265
Reg. Date: 03/06/2019

Estimate Repair Cost to Vehicle No :SML7843X

Description	U/Price	Quantity	List Price	Amount
			SS	SS
36 FRONT GRILLE INNER	205.10	1 PC	205.10	X
37 FRONT GRILLE LOGO	95.50	1 PC	95.50	2
38 FRONT HEADLAMP - LH	1,450.80	1 PC	1,450.80	X
39 FRONT HEADLAMP - RH	1,450.80	1 PC	1,450.80	2
40 FRONT SUPPORT PANEL	676.80	1 PC	676.80	2
41 FRONT SUPPORT PANEL TOP GARNISH	100.00	1 PC	100.00	X
42 FRONT SUPPORT PANEL TOP GARNISH CLIPS	50.00	1 SET	50.00	X
43 RADIATOR	1,650.40	1 PC	1,650.40	X
44 RADIATOR COOLANT	60.00	1 PC	60.00	X
45 RADIATOR BRACKET - LH	49.60	1 PC	49.60	X
46 RADIATOR BRACKET - RH	49.60	1 PC	49.60	X
47 RADIATOR FAN	127.70	1 PC	127.70	X
48 RADIATOR FAN COWLING	221.40	1 PC	221.40	X
49 RADIATOR FAN MOTOR	430.40	1 PC	430.40	X
50 WASHING TANK	192.00	1 PC	192.00	2
			17,153.60	17,153.60
Labour				
51 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,600.00	1 JOB	1,600.00	500
52 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,500.00	1 JOB	1,500.00	700
53 TO CHECK WIRING FUNCTIONS.	120.00	1 JOB	120.00	200
54 AIRCON GAS	120.00	1 JOB	120.00	100
			3,340.00	3,340.00

Total SS 20,553.60

Add GST @ 7% 1,438.75

Total Amount Payable SS 21,992.35

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND NINE HUNDRED NINETY TWO AND CENTS THIRTY FIVE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	02/12/2022 13:54 (SGT)
Reported by	Both
Date of Accident	29/11/2022 18:45 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	HOUGANG AVE 3 TOWARDS AIRPORT ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML7843X
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	SEAH ZHEN LONG, JEREMY
NRIC No	SXXXX302C
Email Address	jsooemp90@gmail.com
Mobile Phone No	(Phone) +65-97290590
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Fit
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1317

INSURANCE COMPANY

Name of Insurance Company	Auto & General Insurance (Singapore) Pte. Limited.
Policy Number / Cover Note Number	P10645441R00

DRIVER

Name of Driver	SEAH ZHEN LONG, JEREMY
NRIC No	SXXXX302C
Date Of Birth	16/12/1988
Occupation	Indoor



IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Insurer: Budget Direct

Vehicle: SML 7843 X

Policyholder's Signature

Date & Time: 30/11/22 4:50pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 30/11/22 4:50pm

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

7416
2/12/22



Date of accident: 29/11/22 Time: 6:45pm Location: Hougang Ave 3 towards Airport Road
 My Vehicle A: SML 7843X Vehicle B: SMS 6136Z Vehicle C: /
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

Police Report No. F/2022/202/7023

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Yee Auto Ate Ltd

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 30/11/22 4:00pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 30/11/22 4:50pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



GIAMC SketchPlanForm_V3


**SINGAPORE
POLICE FORCE**


F/20221202/7023

1 of 2

POLICE REPORT (NP299)

Report No. F/20221202/7023

Police Station Of Origin
Ang Mo Kio Division HQ
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-2180000

Date/Time Report Made 02/12/2022 11:30	Vide Report No.	Station Diary No.
Name Of Informant SEAH ZHEN LONG, JEREMY	Address 541 HOUGANG AVENUE 8 #05-1213 SINGAPORE 530541	
ID Type / ID No. NRIC NO / S8850302C	Contact No. Home/Office:	Mobile: 97290590
Nationality SINGAPORE CITIZEN	Email Address JSOOEMP90@GMAIL.COM	
Occupation Mechanical engineer	Sex Male	Age 33
Institution/School Name	Date of Birth 16/12/1988	Race Chinese
Date/Time Of Incident 29/11/2022 18:45 - 29/11/2022 18:50	Location Of Incident 541 HOUGANG AVENUE 8 #05-1213 SINGAPORE 530541	

Brief details.

On 29/11/22 at 6.45pm, I was driving my vehicle (A) SML7843X along Hougang Avenue 3 towards Airport road. The traffic light was green and I was going straight. Suddenly, the vehicle (B) SMS6136Z from my right side came out without stop and hit onto my vehicle front portion.

My direction had already turned green for a period of time even before my car approached the junction.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 02/12/2022 11:30
Officer In-Charge Of Case:	Classification Of Case:



**SINGAPORE
POLICE FORCE**



F/20221202/7023

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20221202/7023

There is a yellow-box draw on the ground at that cross-junction.
Basic Driving Theory stated that no vehicles should be inside the yellow to avoid obstructing the road.

SMS6136Z had traveled forward (more than 9 lanes) when the traffic turned from amber to red and he beat the red light which led to him caught in the yellow box and suddenly dashed from my right as I was travelling ahead on green light.

Pls refer to the records for the truth facts.

After the incident, i feeling not well and went to see doctor and given me 4 days mc.

Subjects Involved			
Victim			
Person Name	SEAH ZHEN LONG, JEREMY		
ID Type	NRIC NO	ID No	S8850302C
Gender	Male	Age	33
Race	Chinese	Language	English
Occupation	Mechanical engineer	Address	541 HOUGANG AVENUE 8 #05-1213 SINGAPORE 530541
Mobile No	97290590	Is Informant A Victim?	Yes
Person Name	SEAH ZHEN LONG, JEREMY (Informant)		

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:
02/12/2022 11:30

Classification Of Case: