



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                 |                       |
|--|---|-----------------|-----------------------|
| AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)   |   | Ref:            | CS/SPF22012151/Uvy3m4 |
| ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1   |   | Date:           | 20/12/2022            |
| HEMMANT ROAD SINGAPORE 438675  |   |                 |                       |
| ATTN: HAFIZUL FARHAN   |   | Code:           | SPF                   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |                 |                       |
| Insured Veh.   | QX 563P   | Veh. Inspected  | FBA 8020K             |
| Policy No.   |   | Coverage (\$)   | 0.00                  |
| Claim No.  | ACS/105/009/2022/106  | Excess (\$)     | 0.00                  |
| Assign From  | HAFIZUL FARHAN  | Assign Date     | 05/12/2022            |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                 |                       |
| Make & Model   | HONDA ADV150  | c.c             | 149                   |
| Engine No.   | HIDDEN  | Year of Reg.    | 2020                  |
| Chassis No.  | MH1KF6110LK026831   | Colour          | WHITE                 |
| Odometer   | 48019 KM  | Steering        | AFFECTED              |
| Brakes   | IN ORDER  | Modification    | SPORTS RIM            |
| General  | GOOD  |                 |                       |
| <b>3. Conditions of Tyres</b>  |   |                 |                       |
|  | Size  | Make            | Balance               |
| R/H Front Tyre   | 110-70-14   | PIRELLI         | 6 mm                  |
| L/H Front Tyre   |   |                 | mm                    |
| R/H Rear Tyre  | 130-70-13   | PIRELLI         | 6 mm                  |
| L/H Rear Tyre  |   |                 | mm                    |
| <b>4. Description of Damages</b>   |   |                 |                       |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S & N/S BODY.   |   |                 |                       |
| DAMAGES SEE DETAILS.   |   |                 |                       |
| <b>5. General Information</b>  |   |                 |                       |
| Accident Date  | 08/10/2022  | Inspection Date | 05/12/2022            |
| Survey held at   | EROFIA MOTOR TRADING PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#02-62<br>SINGAPORE 417883 |                 |                       |
| <b>5a. Remarks</b>   |   |                 |                       |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                       |
| <b>5b. Estimate Days of Repair</b>   |   |                 |                       |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | 4 Working Days  |                       |