

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: INDIA	DATE	: 1-Dec-22
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SMR4224X		
MODEL	: HONDA SHUTTLE 1.5G		
CHASSIS NO	:		
ACCIDENT DETAILS	DATE : 29-Nov-22		
	TIME : 22:10HR		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BONNET	1	\$ 1,255.30	\$ 1,255.30
2	FRONT BUMPER	1	\$ 1,150.60	\$ 1,150.60
3	FRONT BUMPER SIDE RETAINER	2	\$ 62.40	\$ 124.80
4	FRONT BUMPER TOWING COVER	1	\$ 50.00	\$ 50.00
5	FRONT BUMPER LOWER GRILLE	1	\$ 210.90	\$ 210.90
6	FRONT BUMPER REINFORCEMENT	1	\$ 420.00	\$ 420.00
7	FRONT BUMPER DAYLIGHT	2	\$ 558.20	\$ 1,116.40
8	FRONT BUMPER DAYLIGHT HOUSING	2	\$ 210.80	\$ 421.60
9	FRONT CENTRE GRILLE	1	\$ 322.40	\$ 322.40
10	FRONT CENTRE GRILLE LOGO	1	\$ 60.00	\$ 60.00
11	FRONT CENTRE GRILLE LOGO CHROME	1	\$ 411.90	\$ 411.90
12	CENTRE GRILLE LOWER CHROME	1	\$ 266.30	\$ 266.30
13	FRONT HEAD LAMP	2	\$ 2,455.60	\$ 4,911.20
14	FRONT HEADLAMP LOWER BRACKET	2	\$ 75.20	\$ 150.40

1747.10
2015-1397-68

TOTAL PRICE \$ 10,871.80

LESS 20% \$ 2,174.36

SUB TOTAL PRICE \$8,697.44

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

1	FRONT NUMBER PLATE	1	\$ 50.00	\$ 50.00	X
2	FRONT BUMPER CLIP (SET)	1	\$ 20.00	\$ 20.00	me

TOTAL \$70.00

20

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,000.00		200
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00		200
3	TUFF COAT	\$ 100.00		X
4	WIRING CHECK	\$ 250.00		X
5	CONDUCT WATER LEAKAGE TEST	\$ 100.00		X
TOTAL		\$2,450.00		

400

ESTIMATE REPORT

TOTAL PARTS COST : \$8,767.44
TOTAL LABOUR COST : \$2,450.00
TOTAL REPAIR COST : \$11,217.44

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

1397.68
20

400

1817.68

1/5/1450

2 days
X

Tanfiah 9749547 / 62563561
'wp' 07/12/22 E 2/2
L/S Resurvey after repair
Tanfiah C. Khawar
-2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: