

08/11/23 Wof
ASS. REC. BY: pm

REF:

CC4/AS22012187/Rp23

580H

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / T / F / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLB 25394

at Workshop m/s MOTOR IMAGE

of 25, Lench KEG RD

Insured: AIS

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

11-12

Remark The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: 51K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLB 25394 Yr Regn: 2016 / MAR

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: SUBARU XV 1.6T-S AWD cc 1600

Colour: BLACK A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: 142047 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: JF14P3KC544164884

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 225/55R17

R: _____

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

☒ TOYO / ☒ YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 03/12/22 D.O.I. 07/12/22

Survey held at MOTOR IMAGE

Des. of Damages: ☐ Fnt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR HAT - 26K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

) S + RS \$ _____

☐ : Interview (\$ _____)

) Photos

☐ : Tech. Invs (\$ _____)

) Others

☐ : Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0268/2022
DATE : 05-DEC-2022

ALLIANZ INSURANCE COMPANY OF SINGAPORE PTE LTD
3 TEMASEK AVENUE
#09-01 CENTENNIAL TOWER
S(039190)
TEL : 6297 2529
FAX : 6395 3768/6297 1956

OWNER'S NAME : LI YULONG
ADDRESS : APT BLK 274B COMPASSVALE BOW
#14-525
S(542274)
TELEPHONE NO : 9021 6359

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1
VEHICLE NO : SLB2539Y
MODEL CODE : GP3EKDC
MODEL/YEAR : XV 1.6I-S AWD CVT
ENGINE NO : FB16Y112284
CHASSIS NO : JF1GP3KC5GG164884
MILEAGE : 1 KM
DATE IN : 05/12/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 05/12/2022

Print Date : 05/12/2022
Print Time : 19:04:55

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLB2539Y

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST ALLIANZ INS (SMN2559P)		
2 ZZ/001	DOA:03/12/2022 TIME:1930 HRS LOCATION:278 COMPASSVALE BOW CARPARK DECK 2A		
3 ZZ/002	REPLACE FRONT HOOD, FRONT BUMPER, ENERGY ABSORBER, LH FENDER & SUPPORT PANEL <i>elox</i>	3100.00	<i>1800</i>
4 ZZ/003	RESPRAY FRONT HOOD, FRONT BUMPER, LH FENDER AND SUPPORT PANEL <i>es20x3</i>	2160.00	<i>1560</i>
5 ZZ/004	REMOVE & REFIX FRONT HEADLAMP WASHER & PIPING	150.00	/
6 ZZ/005	REMOVE & REFIX A/CON CONDENSER & RADIATOR TO FACILITATE REPAIR	220.00	X
7 ZZ/006	A/CON GAS & COOLANT	100.00	X
8 ZZ/007	4 WHEEL ALIGNMENT	220.00	X
9 ZZ/008	TRANSFER/BALANCE TYRE/RIMS	50.00	X
10 ZZ/009	TO CONDUCT (FRONT) LIGHTING TEST	50.00	/
11 ZZ/011	SUNDRIES	100.00	<i>20</i>
12 ZZ/10	FAULT DIAGNOSTIC (RESET)	280.00	/
	TOTAL LABOUR CHARGES	6430.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLB2539Y

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	DISC WHEEL AL 17 C67 <i>X</i>	28111FJ170	1500.00			
2	RAD PNL COMPL RPR <i>repair</i>	53029FJ0009P	536.50			
3	FENDER F XUV LH <i>bu✓</i>	57120FJ0619P	203.50			
4	HOOD COMPLETE-FRONT <i>X</i>	57229FJ0009P	555.00			
5	BUMPER FACE F XUV <i>de✓</i>	57704FJ070	425.50			
6	ENR ABSORB FOAM XU <i>cm✓</i>	57705FJ010	81.40			
7	BRKT FRH BUMP CORN <i>? X</i>	57707FJ001 <i>n/s</i>	44.40			
8	BRKT FLH BUMP CORN <i>cm✓</i>	57707FJ011 <i>n/s</i>	44.40			
9	BRKT BUMP FRH <i>X</i>	57707FJ140 <i>n/s</i>	7.40			
10	BRKT BUMP FLH <i>cm✓</i>	57707FJ150 <i>n/s</i>	7.40			
11	BACK BEAM COMPL-F <i>bt✓</i>	57711FJ0519P	266.40			
12	COVER HOOK F <i>X</i>	57731FJ460 <i>n/s</i>	4.80			
13	LAMP ASSY HEAD EHL <i>bu✓</i>	84001FJ630	876.90			
14	TANK <i>cm✓</i>	86631FJ120	74.00			
15	CLIP 2 PCS <i>cm✓</i>	909140062	6.00			
16	GARNISH FRONT FENDER LH <i>de✓</i>	91112FJ111	185.00			
SUB TOTAL			4818.60	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			963.72	0.00	0.00	0.00
GRAND TOTAL			3854.88	0.00	0.00	0.00
OVERALL TOTAL			3854.88			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLB2539Y

TOTAL LABOUR CHARGES	6430.00
TOTAL SPARE PARTS CHARGES	3854.88
GRAND TOTAL	10284.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - Hp 90010068
SURVEYED DATE	:	07/12/22 @ 1200
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 6 days
LIABILITY	:	0.00
REMARKS	:	Resurvey before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 580H

Vehicle Details

Vehicle No.: SLB2539Y

Vehicle to be Exported: No

Intended Deregistration Date: 08 Dec 2022

Vehicle Make: SUBARU

Vehicle Model: SUBARU XV 1.6I-S AWD CVT

Primary Colour: Black

Manufacturing Year: 2015

Engine No.: FB16Y112284

Chassis No.: JF1GP3KC5GG164884

Maximum Power Output: 84.0 kW (112 bhp)

Open Market Value: \$15,274.00

Original Registration Date: 31 Mar 2016

First Registration Date: 31 Mar 2016

Transfer Count: 0

Actual ARF Paid: \$15,274.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 30 Mar 2026

PARF Rebate Amount: \$9,928.00

Intended COE Rebate Details

COE Expiry Date: 30 Mar 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$45,504.00

COE Rebate Amount: \$15,057.00

Total Rebate Amount: \$24,985.00

Subaru XV 1.6i-S

Overview

Financial

Accessories

Similar

Research

Photos

Map



HARVEST MOTORING

Price	\$53,999		
Depreciation	\$13,340 /yr View models with similar depre	Reg Date	23-May-2016 (3yrs 5mths 14days COE left)
Mileage	113,888 km (17.4k /yr)	Manufactured	2016
Road Tax	\$744 /yr	Transmission	Auto
Dereg Value	\$26,847 as of today (change)	OMV	\$15,849
COE	\$47,889	ARF	\$15,849
Engine Cap	1,600 cc	Power	84.0 kW (112 bhp)
Curb Weight	1,480 kg	No. of Owners	2