Mei Kwan (LKKAuto)

Date of Survey:

Name of Authorise Surveyor:

From: Sent: To: Subject: Attachments:	Susan Low < liusbro@ymail.com> Tuesday, 6 December 2022 3:36 PM Admin A Our Ref: GBC8283H221205 Your Ref: SLW8602Y GBC8283H221205.pdf; GBC8283H Search.pdf	
Follow Up Flag: Flag Status:	Follow up Flagged	
Categories:	НМК	
We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.		
Vehicle to be surveyed:	GBC8283H	
3rd Party Insured Vehicle:	SLW8602Y	
Date of Accident:	05/12/2022	
Location of Accident:	Junction Of Bishan Street 21 And Marymount Lane	
Name of Workshop:	Liu's Brother Auto Engineering Workshop	
Address of Survey Location:	No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883	
Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop as soon as possible Kindly arrange Thank you.		
Best Regard		
Susan Low		
M/s Liu's Brother Auto Workshop		
No. 1 Kaki Bukit Avenue 6 #01-01		
AutoBay @ Kaki Bukit Singapore 417883		
Olligapore + 17000		
Tel: 6741 1730		

