

Our Job Ref No : 305538538

Date 08.12.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr NAZ


Vehicle Reg No. SHB2337K

Date of Accident : 02.12.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill 703A INCOME FBT5361X
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges
- Total for Part-By-Part Repair Cost**
- (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% **\$1,250.00**
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.


We confirm the estimates and
finalized amount

Signature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : 

Name : NAZ

Date : 13/12/2022

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

REPAIR ESTIMATE*

MODEL IONIO

DOA: 02.12.22

INCOME[illegible]