

ASS. REC. BY:

REF:

CS/AIS22012228/Kny3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 / Est not ready, David said part by part, unable to locate 2nd parts

01/02/23 Kenneth confirmed final fig: \$2426.10 and 4 days

(red, \$867.5, 26%)

Date/Time, File Pass to?

1) 01/02/23

Date/Time, File Return to?

2)

☐

Prell. Report

☐

Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Report Format:

od

Lump Sum / I.B.I. (\$

2426.10

Veh No:

SUB 8922M

Yr Regn:

09, 6

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Hyundai Elantra S.c.c

1591

Colour

M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading

94224

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH0841CMHU238620

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / R/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Nexen

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

30/11/22

D.O.I.

1/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.