



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD	Ref: NS/INC22012230/Nvp3m4
75 BRAS BASAH ROAD	Date: 14-12-2022
INCOME CENTRESINGAPORE 189557	Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 9920B	Veh. Inspected	SHB 4789B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1200353-001	Excess (\$)	0.00
Assign From		Assign Date	05/12/2022

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ G3	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVLU178618	Colour	YELLOW
Odometer	271490	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	4 mm
L/H Front Tyre	195/65 R15	WEST LAKE	4 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/12/2022	Inspection Date	05/12/2022
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------