

Our Job Ref No : 305538555
Date : 07/12/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr Naz
Vehicle Reg No. : SHB4789B


Fax :


03.12.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **INCOME** -- **GBB9920B**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost** **\$0.00**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: **20%** **\$800.00**
Final Lumpsum Repair cost **\$800.00**
3. Estimated normal period for repairs: **2** working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : Ms. Loke YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : NAZ LKK
Date : 7/12/2022

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD
REPAIR ESTIMATE

Vehicle No. : SHB4789B

Make : HYUNDAI

Model : IONIQ(G3)

Date: 05.12.2022

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	FRT BUMPER			\$ 481.10	✓ CUT
1	FRT BUMPER REINFORCEMENT			\$ 1,136.70	? X SVC
1	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50	? X SVC
10	FRT BUMPER CLIPS			\$ 22.00	✓ NE
1	HEADLAMP RH			\$ 2,110.30	? X SVC
1	FRT BUMPER TOWING COVER			\$ 29.00	? X SVC
	SUB TOTAL			\$ 4,147.60	
	LESS 20%			\$ 829.52	
	DISCOUNTED TOTAL			\$ 3,318.08	
					Nett
				\$ -	nett
	Labour Charge				
	PANEL BEATING			\$ 400.00	350
	SPRAY PAINTING CHARGE			\$ 300.00	250
	CHECK ALL LIGHTING			\$ 60.00	XNN
	TOTAL LABOUR			\$ 700.00	
	Emblem-Blue Drive (LH/RH)				
	ESTIMATE TOTAL			\$ 4,018.08	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LKK
 5/12/2022 1620
 LIS
 2 DAYS
 CHECK ITEM PHOTO
 AFTER REPAIR PHOTOS

Auto Consultants hence notify
 Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: