

ASS. REC. BY: NA2

REF:

INC

LIM PIP

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SH 8212 K Yr Regn: 14 APR 2022

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA PRIMS HYBRID c.c. 1,798Colour: BLUE A/C: Insured Std / NI / NASp. Reading: 66,132 T/Radio: Insured Std / NI / NA

Eng/No: _____

C/No: 3TDKB3FU503093062

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD / Rim orTyre Size: F: 195/65 R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAK (F) DUN (R)

Front

Rear

R/Bal. 6 mmR/Bal. 3 mmL/Bal. 6 mmL/Bal. 3 mmD.O.A. 2/12/2022D.O.I. 5/12/2022

Survey held at

EDGE LOYANGDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1) _____
Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL