

**COMFORTDELGRO
ENGINEERING**ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305538882

Date : 10/12/22

FINALIZATION FORM

To : LKK



Fax :

Attn : Mr NAZ

Vehicle Reg No. : SH 9120K

06.12.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **TOKIO MARINE** -- **SLP4936Y**
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges
- Total for Part-By-Part Repair Cost** **\$0.00**
- (c) Lumpsum Repair (if applicable)
- Total for Lumpsum repair cost after Less: 20% **\$1,650.00**
- Final Lumpsum Repair cost** **\$1,650.00**
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.
- We confirm the estimates and finalized amount
- Signature : 
- Signature : 
- Name : Ms. Loke YY
- Name : NAZ LKK
- Tel : 62148355
- Date : 16/12/2022
- Fax : 65468156

For Official Use Only

| Item | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|-----------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day | | YES | | |
| 2. Loss of Income Paid | | NO | | |
| 3. Survey Fees | | | | |
| 4. LTA Search Fee | \$7.49 / \$2.00 | | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | |
| 6 Overrun | | | | |

Remarks:

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Loke Wei Yiang

Singapore

PARTICULARS OF CLAIM

| | | | |
|-------------------|----------------|---------------|------------|
| Claim Type: | THIRD PARTY | Ref. No: | |
| Policy No: | | Date of Loss: | 06/12/2022 |
| Vehicle Reg. No.: | SH9120K | Driveable? | YES |
| Party At Fault: | UNKNOWN | | |

| | | | |
|-----------------|---------------------------------------|--------------------|-------------------|
| Make/Model: | HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) | Vehicle Reg. Date: | 17/03/2017 |
| Vehicle Colour: | BLUE | Gen Condition: | GOOD |
| Engine No: | G4LEGU329699 | Chassis No: | KMHC851CVHU022742 |
| Odometer: | 900202 KM | | |

Paint Type:

List Item Discount: 20.00 %

Total Loss? **NO**

Est. Duration of Repair (day) 4

Remarks: TEL: 62148355

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

| | Amount |
|---------------------------|-----------------|
| Parts | 1,961.52 |
| Miscellaneous Items | 11.00 |
| Labour | 780.00 |
| Paintwork Labour | 0.00 |
| Towing | 0.00 |
| Gross Total (\$\$) | 2,752.52 |
| + GST 7.00% (\$\$) | 192.68 |
| Nett Amount (\$\$) | 2,945.20 |

This claim is handled by: MS. LOKE YY

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Dec 2022)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH9120K/07/12/2022 09:25

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|-----|-----|----------|---------------------------------------|-------|-------|-----------------|
| 1 | 1 | | *REAR BUMPER COVER | 20.00 | 0.00 | *459.40 FL/BUC |
| 2 | 1 | | *REAR BUMPER CLIPS | 20.00 | 0.00 | *22.00 FLXNN |
| 3 | 1 | | *REAR BUMPER CENTRE MOULDING ASSY | 20.00 | 0.00 | *451.25 FL/BUC |
| 4 | 1 | | *REAR BUMPER REINFORCEMENT | 20.00 | 0.00 | *394.80 FL?XSVL |
| 5 | 1 | | *REAR BUMPER REINFORCEMENT BRACKET LH | 20.00 | 0.00 | *138.10 FL?BT |
| 6 | 1 | | *REAR BUMPER REINFORCEMENT BRACKET RH | 20.00 | 0.00 | *138.10 FL?BT |
| 7 | 1 | | *ANTENNA SMARTKEY | 20.00 | 0.00 | *40.50 FL/CRA |
| 8 | 1 | | *REAR BUMPER FOG LAMP | 20.00 | 0.00 | *201.50 FL/CRA |
| 9 | 1 | | *RENEW ADVERTISEMENT STICKER | 0.00 | 0.00 | *200.00 F/NEC |
| 10 | 1 | | *REAR NUMBER PLATE WITH TRIM COVER | 0.00 | 0.00 | *55.00 F/CRA |
| 11 | 1 | | *REAR BUMPER REVERSE SENSOR | 0.00 | 0.00 | *180.00 FX SVL |
| 12 | 1 | | *REAR BUMPER RUBBER MAT | 0.00 | 0.00 | *50.00 F/NEC |

F=Franchise part. L=ListItemDisc.

| | | |
|---------------------------------------|----------|----------|
| Sub Total (S\$) | 1,229.35 | 2,330.65 |
| - List Item Discount on L Items (S\$) | | 369.13 |
| Total Parts (S\$) | 981.88 | 1,961.52 |

ComfortDelGro Engineering Pte Ltd/SH9120K/07/12/2022 09:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

728.52

Estimates on Miscellaneous Items

| No | Qty | Particulars | Amount |
|----------------------------|-----|----------------------|--------|
| Miscellaneous Items | | | |
| 1 | 1 | OD/TP Case (Insurer) | 11.00 |
| Sub Total (\$\$) | | | 11.00 |

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|--------------------------|-----------------------------|----------|-----------------------|
| Labour Items | | | |
| 1 | PANEL BEATING | New | 400.00 350 |
| 2 | SPRAY PAINTING CHARGE | New | 300.00 250 |
| 3 | REMOVE/REFIX REVERSE SENSOR | New | 80.00 30 |
| Gross Labour Cost (\$\$) | | | 780.00 |

ComfortDelGro Engineering Pte Ltd/SH9120K/07/12/2022 09:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NAZ LKK
7/12/2022 1530
LIS
2 DAYS
CHECK ITEM (PHOTO)
AFTER REPAIR PHOTOS

1,927.58

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: