

Our Job Ref No : 305538745  
Date 08.12.22

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

**FINALIZATION FORM**


To : LKK  
Attn : Mr NAZ


Fax :

Vehicle Reg No. sh 8323z Date of Accident : 03.12.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill 703A INCOME sba4108t
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges
  - Total for Part-By-Part Repair Cost
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$1,400.00  
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature :   
Name : JUMANI  
Tel : 62148315  
Fax : 65468156

Signature :   
Name : NAZ  
Date : 13/12/2022

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305538745  
REGN NO : SH 8323Z  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 14.11.2019  
DATE/TIME IN : 03.12.2022 18:55  
ACCIDENT DATE : 03.12.2022

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0104-2537-G	MIRROR ASSY-O/S RR VIEW L	1	1,391.70	20.00	1,113.36	1 CRA
0002 04-01-0104-2694-G	GLASS ASSY-FRONT DOOR LH	1	215.20	20.00	172.16	1 SCR
SUB-TOTAL :						1,285.52

## JOB NATURE

0000 PB	PANEL BEATING	<del>400.00</del>	350
0001 SP	SPRAYPAINT CHARGE	<del>120.00</del>	100
0002 23-01	TOWING FEE	<del>60.00</del>	0
SUB-TOTAL :		580.00	
TOTAL :		1,865.52	

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

NAZ LKK  
6/12/2022 1600  
L1  
2 Days  
AFTER CLEAR PHOTOS

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: