

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305538745
 REGN NO : SH 8323Z
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 14.11.2019
 DATE/TIME IN : 03.12.2022 18:55
 ACCIDENT DATE : 03.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2537-G MIRROR ASSY-O/S RR VIEW L 1 1,391.70 20.00 1,113.36 /CRA
 0002 04-01-0104-2694-G GLASS ASSY-FRONT DOOR LH 1 215.20 20.00 172.16 /SCR

SUB-TOTAL : 1,285.52

JOB NATURE

0000 PB PANEL BEATING
 0001 SP SPRAYPAINT CHARGE
 0002 23-01 TOWING FEE

~~400.00~~ 350
~~120.00~~ 100
~~60.00~~ 50

SUB-TOTAL : 580.00

TOTAL : 1,865.52

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

NAZ LKK
 6/12/2022 1600
 L1
 2 Day
 AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: