

08/11/11 Wef

ASS. REC. BY: Rome

REF:

CC3/AIG22012266/Rqp3

0002

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: SLS 66165

at Workshop m/s Premium

of 24, Brown & Green

Insured: MH

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: TBA 900

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|---|-----|
|  | |
| N/S | O/S |
| | |

Bal. or Market Value: 125K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLS 66165 Yr Regn: 2018 1 July

Type: ☒ M/Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Audi A6 1.8 TFSI (V6) c.c. 1798

Colour: WHITE A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: 62637 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng No: _____

C/No: WAUZZZ4G2JN060338

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 225/55R17

R: _____

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 04/12/22 D.O.I. 07/12/22

Survey held at: PREMIUM

Des. of Damages: ☒ Fnt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 68K

Rasul finalised final fig \$39666.52, 10 days. (Red \$39140.48, 50%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : MER-OD

Lump Sum / I.B.I. (\$) 39666.52

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01091/2022/EQ
DATE : 7-Dec-22
WIP : 53631

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR PEH CHYE HENG
ADDRESS : 8 CACTUS DRIVE
#03-03
SINGAPORE 809686
TELEPHONE : HP +65 97329181
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800110079-02
VEHICLE NO : **SLS 6616 S**
MODEL CODE : AUDI A6 1.8 TFSI S-TRONIC
MODEL YEAR : 30/8/2018
ENGINE NO : CYG 024756
CHASSIS NO : WAUZZZ4G2JN060338
MILEAGE : 62,637
DATE IN : 5-Dec-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Dec-22
PLACE OF ACCIDENT : LEBUHRAYA UTARA-SELATAN, TAMAN SERDANG
RAYA, SERI KEMBANGAN, SELANGOR, MALAYSIA

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 6616 S

| S/N | NATURE OF JOBS | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--|--------------------------|----------------------------|
| 1 | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N \$ 480.00 / | |
| 2 | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE. | S/N \$ 800.00 250 | |
| 3 | TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. | S/N \$ 1,600.00 / | |
| 4 | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | @500X45 \$ 6,400.00 2250 | |
| 5 | TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BOTH FRONT FENDER, BONNET AND HINGES. | @550X45 \$ 5,000.00 2475 | |
| TOTAL LABOUR CHARGES | | : \$ 14,280.00 | |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 6616 S

| S/N | NATURE OF JOBS | | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--|----------|----------------------|-------------------------------|
| 6 | TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION. | S/N \$ | 480.00 | / |
| 7 | TO CARRY OUT PRE/POST DIAGNOSTIC CHECK. | S/N \$ | 384.00 | / |
| TOTAL LABOUR CHARGES | | : | \$ 15,144.00 | |

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 6616 S

| | | | DAMAGED PARTS & PRICES | |
|------------------------------|--|----------|------------------------|---------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 1 | FRONT BUMPER <i>de-</i> | 1 | \$ 3,475.00 | |
| 2 | FRONT BUMPER FIXING PARTS <i>X</i> | 1 | \$ 567.00 | |
| 3 | FRONT BUMPER GRILLE - LOWER CENTRE <i>?</i> | 1 | \$ 143.00 | |
| 4 | FRONT BUMPER ADAPTER - LH / RH <i>?</i> | 2 | \$ 84.00 | |
| 5 | FRONT BUMPER CLOSING ELEMENT <i>cm</i> | 1 | \$ 237.00 | |
| 6 | FRONT BUMPER LOWER SPOILER <i>repair</i> | 1 | \$ 276.00 | |
| 7 | FRONT BUMPER LOWER TRIM SPOILER <i>X</i> | 1 | \$ 1,054.00 | |
| 8 | RADIATOR GRILLE <i>cm</i> | 1 | \$ 2,140.00 | |
| 9 | RADIATOR GRILLE COVER <i>?</i> | 1 | \$ 41.00 | |
| 10 | RADIATOR GRILLE SENSOR SUPPORT - LH / RH <i>cm</i> | 2 | \$ 148.00 | |
| 11 | FRONT PARKING AID SENSOR - INNER <i>?</i> | 2 | \$ 531.00 | |
| 12 | FRONT PARKING AID SENSOR - OUTER <i>?</i> | 2 | \$ 531.00 | |
| 13 | FRONT PARKING AID SEAL RING <i>cm</i> | 4 | \$ 6.00 | |
| 14 | FRONT BUMPER WIRING SET <i>?</i> | 1 | \$ 642.00 | |
| 15 | FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>cm</i> | 2 | \$ 1,286.00 | |
| 16 | FRONT CHANNEL COVER - LH / RH <i>cm</i> | 2 | \$ 116.00 | |
| 17 | FRONT WHEEL SPOILER - LH / RH <i>?</i> | 2 | \$ 588.00 | |
| 18 | FRONT BUMPER REINFORCEMENT BEAM <i>?</i> | 1 | \$ 927.00 | |
| 19 | FRONT BUMPER FOAM FILLER PIECE <i>?</i> | 1 | \$ 265.00 | |
| 20 | FRONT BUMPER BRACKET HOLDER - LH / RH <i>?</i> | 2 | \$ 582.00 | |
| SUB TOTAL SPARE PARTS | | : | \$ 13,639.00 | |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 6616 S

| | | | DAMAGED PARTS & PRICES | |
|------------------------------|---|-----|------------------------|---------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 21 | FRONT BUMPER BRACE - LH / RH ? | 2 | \$ 68.00 | |
| 22 | FRONT BUMPER GUIDE PIECE - LH / RH ? | 2 | \$ 84.00 | |
| 23 | FRONT BUMPER TOP COVER <i>con</i> | 1 | \$ 137.00 | |
| 24 | AIR CONDITIONER STICKER <i>re</i> | 1 | \$ 22.00 | |
| 25 | CAUTION SIGN STICKER <i>re</i> | 1 | \$ 16.00 | |
| 26 | HORN LOW TONE - LH ? | 1 | \$ 214.00 | |
| 27 | HORN HIGH TONE - RH ? | 1 | \$ 214.00 | |
| 28 | HORN BRACKET - LH / RH ? | 2 | \$ 106.00 | |
| 29 | FRONT FENDER - LH / RH <i>Repair</i> | 2 | \$ 3,120.00 | |
| 30 | FRONT FENDER ATTACHMENT PARTS X | 1 | \$ 107.00 | |
| 31 | FRONT FENDER BRACE - LH / RH X | 2 | \$ 214.00 | |
| 32 | FRONT DOOR STONE GUARD FILM - LH / RH <i>re</i> | 2 | \$ 270.00 | |
| 33 | FRONT WHEEL HOUSING LINER - LH / RH ? | 2 | \$ 620.00 | |
| 34 | BONNET <i>bt</i> | 1 | \$ 5,736.00 | |
| 35 | BONNET HINGE - LH / RH ? X | 2 | \$ 358.00 | |
| 36 | BONNET CATCH HOOK ? | 1 | \$ 155.00 | |
| 37 | BONNET LOCK - LH / RH <i>bt</i> | 2 | \$ 455.00 | |
| 38 | BONNET LOCK BAR - LH / RH ? | 2 | \$ 111.00 | |
| 39 | BONNET BOWDEN CABLE - CENTER ? | 1 | \$ 64.00 | |
| 40 | BONNET RELEASE CABLE COVER ? | 1 | \$ 11.00 | |
| SUB TOTAL SPARE PARTS | | : | \$ 12,082.00 | |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 6616 S

| | | | DAMAGED PARTS & PRICES | |
|------------------------------|---|-----|------------------------|---------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 41 | BONNET LOCK COVER ? | 1 | \$ 4.00 | |
| 42 | BONNET CATCH HOOK ? | 1 | \$ 20.00 | |
| 43 | BONNET LOCK CABLE ? | 1 | \$ 82.00 | |
| 44 | HEADLIGHT MOUNTING - LH / RH <i>Ca</i> | 2 | \$ 264.00 | |
| 45 | HEADLIGHT - LH <i>Ca</i> / RH <i>Ca</i> | 2 | \$ 20,294.00 | |
| 46 | HEADLIGHT POWER MODULE ? | 1 | \$ 635.00 | |
| 47 | HEADLIGHT POWER MODULE ? | 1 | \$ 625.00 | |
| 48 | HEADLIGHT RANGE CONTROL MOTOR ? | 1 | \$ 362.00 | |
| 49 | HEADLIGHT FAN - RH ? | 1 | \$ 428.00 | |
| 50 | HEADLIGHT HOSE ? | 1 | \$ 40.00 | |
| 51 | HEADLIGHT ADJUSTMENT ELEMENT - LH / RH <i>Ca</i> | 2 | \$ 102.00 | |
| 52 | HEADLIGHT COMPENSATING PIECE <i>RH - Ca / LH - ? 2</i> | 2 | \$ 185.00 | |
| 53 | LIFT CYLINDER - LH / RH ? | 2 | \$ 518.00 | |
| 54 | LIFT CYLINDER COVER CAP - LH / RH ? | 2 | \$ 128.00 | |
| 55 | LIFT CYLINDER HOSE ? | 1 | \$ 553.00 | |
| 56 | LOCK CARRIER <i>Ca</i> | 1 | \$ 1,385.00 | |
| 57 | LOCK CARRIER SUPPORT - LH / RH ? | 2 | \$ 83.00 | |
| 58 | CHARGE AIR COOLER ? | 1 | \$ 628.00 | |
| 59 | PULSATION DAMPER <i>X</i> | 1 | \$ 88.00 | |
| 60 | CHARGE AIR COOLER PRESSURE PIPE - LH <i>X</i> | 1 | \$ 262.00 | |
| SUB TOTAL SPARE PARTS | | | \$ 26,686.00 | |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 6616 S

| | | | DAMAGED PARTS & PRICES | |
|----------------------|---|-----|------------------------|--------------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 61 | CHARGE AIR COOLER PRESSURE HOSE X | 1 | \$ | 76.00 |
| 62 | A/C CONDENSER bt ✓ | 1 | \$ | 829.00 |
| 63 | A/C CONDENSER REFRIGERANT HOSE ? | 1 | \$ | 286.00 |
| 64 | A/C CONDENSER REFRIGERANT PIPE ? | 1 | \$ | 286.00 |
| 65 | OUTSIDE TEMPERATURE SENSOR BRACKET ? | 1 | \$ | 26.00 |
| 66 | RADIATOR bt - photo? | 1 | \$ | 897.00 |
| 67 | READY-MIX COOLANT re ✓ | 6 | \$ | 297.00 |
| 68 | RADIATOR AIR GUIDE - LH / RH cool ✓ | 2 | \$ | 172.00 |
| 69 | RADIATOR AIR GUIDE SEALING STRIP ? | 1 | \$ | 54.00 |
| 70 | RADIATOR AIR GUIDE COVER - UPPER CENTRE ? | 1 | \$ | 32.00 |
| 71 | INTAKE AIR DUCT - RH X | 1 | \$ | 101.00 |
| 72 | RADIATOR AIR GUIDE - RH X | 1 | \$ | 31.00 |
| 73 | FRONT DISTANCE SENSOR - RH ? | 1 | \$ | 7,495.00 |
| 74 | FRONT DISTANCE SENSOR FRAME COVER - RH ? | 1 | \$ | 15.00 |
| 75 | FRONT NO PLATE bt ✓ | S/N | \$ | 60.00 |
| 76 | SUNDRIES ? | | \$ | 500.00 |
| TOTAL SPARE PARTS | | | : | \$ 63,564.00 |
| TOTAL LABOUR CHARGES | | | : | \$ 15,144.00 |
| GRAND TOTAL | | | : | \$ 78,708.00 |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Resue - 4p 90010068*
SURVEYED DATE : *6/12/22 P 1630*
AUTHORISED DATE :
EXCESS COST : *10 days*
LIABILITY : *EXCESS: TBA*
REMARKS : *Revert Resue before paint*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 05/12/2022 19:05 (SGT)
Reported by Both
Date of Accident 04/12/2022 22:20 (SGT)
Exact Location of Accident Lebuhraya Utara-Selatan, Taman Serdang Raya, Seri Kembangan, Selangor, Malaysia
Additional Location Information -
Country/State of Loss Malaysia

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLS6616S

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner PEH CHYE HENG
NRIC No SXXXX000Z
Email Address DESMONDPEHCH@GMAIL.COM
Mobile Phone No (Phone) +65-97329181
Alternative Phone No +65-89164079

VEHICLE PARTICULARS

Manufacturer Audi
Model A6
Variant 1.8
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1798

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number 1800110079-02

DRIVER

Name of Driver PEH CHYE HENG
NRIC No SXXXX000Z
Date Of Birth 24/03/1963

Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

Outdoor
18/07/1986
36 YEARS AND 5 MONTHS
Male
(Phone) +65-97329181
+65-89164079
DESMONDPEHCH@GMAIL.COM
8 CACTUS DRIVE
#03-03
809686
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
Weather Conditions Clear
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Yes
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No
Translator's name -
Translator's ID -
Translator's phone number -
Translator's email -
Original language used in the statement -

FOREIGN VEHICLE 1

Vehicle Registration Number SY9231
Vehicle Category Private car

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
Police Station Name MALAYSIA
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

THE VEHICLE IN FRONT OF SY9231 JAMMED THE BRAKE. FOLLOWED BY SY9231 JAMMING THE BRAKE TWICE. I BRAKE TOO BUT COLLIDED WITH SY9231.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SY9231

| | |
|---|-------------|
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Private car |
| Name of Driver | - |
| Contact Number | - |
| Address | - |
| Address complement | - |
| Postcode | - |
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | - |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Tony Fong


↑
—SY9231
—SL566165

Describe Circumstances of the Accident


VEHICLE IN FRONT OF SY 9231 JAMMED BRAKE
 FOLLOWED BY SY 9231 JAMMING BRAKE TWICE
 / BRAKED TOO LATE COLLIDED ONTO SY 9231.

Declaration

We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date &
 Time

Driver's Signature (If driver is not the policyholder) / Date
 & Time


 Witnessed by Reporting Centre
 Personnel Tony Fung

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC

Owner ID: 000Z

Vehicle No: SL566165

Vehicle to be Exported: No

Intended Deregistration Date: 08 Dec 2022

Vehicle Make: AUDI

Vehicle Model: A6 1.8 TFSI ULTRA (PI) (NAV)

Primary Colour: White

Manufacturing Year: 2017

Engine No.: CYG024756

Chassis No.: WAUZZZ4G2JN060338

Maximum Power Output: 140.0 kW (187 bhp)

Open Market Value: \$40,761.00

Original Registration Date: 30 Aug 2018

First Registration Date: 30 Aug 2018

Transfer Count: 0

Actual ARF Paid: \$49,066.00

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Aug 2028

PARF Rebate Amount: \$36,799.00

COE Expiry Date: 29 Aug 2028

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$34,381.00

COE Rebate Amount: \$19,676.00

Total Rebate Amount: \$56,475.00

The Information contained herein is correct as at 08 Dec 2022

OK

Audi A6 1.8A TFSI Ultra

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

| | | | |
|------------------------|--|------------------------|--|
| Price | \$111,800 | | |
| Depreciation ⓘ | \$18,910 /yr View models with similar depre | Reg Date | 11-Sep-2017 (4yrs 9mths 2days COE left) |
| Mileage | 115,000 km (21.9k /yr) | Manufactured ⓘ | 2016 |
| Road Tax ⓘ | \$976 /yr | Transmission | Auto |
| Dereg Value ⓘ | \$53,830 as of today (change) | OMV ⓘ | \$40,419 |
| COE ⓘ | \$49,000 | ARF ⓘ | \$43,587 |
| Engine Cap | 1,798 cc | Power | 140.0 kW (187 bhp) |
| Curb Weight ⓘ | 1,645 kg | No. of Owners ⓘ | 1 |
| Type of Vehicle | Luxury Sedan | | |