

(08/11/13) wef

ASS. REC. BY: Rama

REF:

CS/CT122012297/Rap3

7412

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 101Eat Workshop m/s Amosprint P/Lof 24, Lenth K&E RD #07-03Insured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 212K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SLR 101EYr Regn: 2017 10CT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MARCELO'S BENZ E300 SE C.C. 1950Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2130132A 242682

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / STD A/Rim orTyre Size: F: 215/35ZR19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 05/12/22D.O.I. 09/12/22Survey held at AmosprintDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Limit - 162K

We will be advising our principal a cost of repair P/P \$15,385.60 /- with 08 days of repair before GST, subject to their approval.

(red, \$3014, 16%)

Date/Time, File Pass to?

1) 12/05/23

Date/Time, File Return to?

2) _____

☐ : Prel. Report☐ : Final ReportDays Of Repair: 8Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I. (\$) _____

QUOTATION

To: Chris Tong
SLR101E, Mercedes Benz,

Our Ref :Q221203
Date :07 Dec 2022

Attn : Chris Tong (86666998)

Dear Sir / Madam,

RE: Quotation for

We are pleased to submit the following quotation for your kind consideration.

Remarks :T/Party Claims SLR101E against GBJ9867E

No.	Description	Qty	UOM	U/P (\$)	Amt (\$)
Ad hoc					
1	Rear Boot Cover <i>4/</i>	1.00		2,000.00	2,000.00
2	Rear Boot Rubber <i>u/</i>	1.00		240.00	240.00
3	Rear Boot Moulding <i>cut/</i>	1.00		160.00	160.00
4	Rear Boot Inner Lock <i>cut/</i>	1.00		280.00	280.00
5	Rear Boot Cover Star Emblem <i>u/</i>	1.00		56.00	56.00
6	Rear Boot Cover E300 Emblem <i>u/</i>	1.00		112.00	112.00
7	Rear Boot Inner Hinge Covers <i>7?</i>	2.00		90.00	180.00
8	Rear Boot Surrounding Garnish <i>X</i>	1.00		256.00	256.00
9	Rear Boot Cover Inner Trim <i>?</i>	1.00		560.00	560.00
10	Rear Bumper <i>de/</i>	1.00		1,680.00	1,680.00
11	Rear Bumper Lower <i>sea/</i>	1.00		304.00	304.00
12	Rear Bumper Reinforcement <i>?</i>	1.00		720.00	720.00
13	Rear Bumper Reflectors <i>LH-7/RH sea/</i>	2.00		48.00	96.00
14	Rear Bumper Sensors <i>dis/</i>	2.00		169.00	338.00
15	Rear Bumper Rivets <i>u/</i>	1.00		120.00	120.00
16	Rear Tail Lamps <i>cut/</i>	2.00		720.00	1,440.00
17	Rear Tail Lamp Brackets <i>?</i>	2.00		80.00	160.00
18	Rear Exhaust Chrome Rims <i>7 RH sea/</i>	2.00		160.00	320.00
19	Labour Charge to straighten & align rear lower end panel, remove & replace the above listed damaged parts <i>0400</i>	1.00		2,200.00	2,200.00
20	Labour Charge to reconnect rear lamp wire hardness, coding & reprogramming systems	1.00		450.00	450.00
21	Labour Charge to remove & reinstall rear boot inner trimmings & attachment to facilitate repair works <i>0400</i>	1.00		120.00	120.00
22	Labour Charge to putty & respray painting same (5 portions)	1.00		2,000.00	2,000.00
23	Rear Boot Cover Hinges <i>7?</i>	2.00		248.00	496.00
24	Rear Boot Cover Rubber Stopper <i>u/</i>	2.00		16.00	32.00
25	Rear End Lower Panel <i>?</i>	1.00		1,440.00	1,440.00

Continue on next page...

QUOTATION

To: Chris Tong
SLR101E, Mercedes Benz,

Our Ref : Q221203
Date : 07 Dec 2022

Attn : Chris Tong (86666998)

Dear Sir / Madam,

RE: Quotation for

We are pleased to submit the following quotation for your kind consideration.

Remarks : T/Party Claims SLR101E against GBJ9867E

No.	Description	Qty	UOM	U/P (\$)	Amt (\$)
-----	-------------	-----	-----	----------	----------

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 9001368

6 days

P/P

09/12/22 @ 1050

Resurvey before paint

email: rasul@lkkauto.com

I have read and agree to the terms and conditions stated in the reverse side of this quotation and authorise AUTOSPRINT Pte Ltd to carry out the above work described. Additional quotation (if any) on subsequent repair found during inspection and diagnostics may be provided.

Subtotal:	15,760.00
GST 7.0% :	1,103.20
Total Amount:	16,863.20

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	06/12/2022 18:15 (SGT)
Reported by	Both
Date of Accident	05/12/2022 15:40 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	WOODLANDS AVE 12
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR101E
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TONG YONG
NRIC No	S8677741Z
Email Address	CHRISTONGYONG@GMAIL.COM
Mobile Phone No	(Phone) +65-86666998
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E200D SE
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1950

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number	MT/00792982

DRIVER

Name of Driver	TONG YONG
NRIC No	S8677741Z
Date Of Birth	04/08/1986
Occupation	Indoor

Date Of Driving Pass	26/04/2011
Driving experience	11 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-86666998
Alt. Phone Number	-
Email Address	CHRISTONGYONG@GMAIL.COM
Address	BLK 541 WOODLANDS DRIVE 16 #12-59
Address complement	-
Postcode	-
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	MEI YI XIN
Gender	Male

PASSENGER 2

Name	LASHMAN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	COLLECT FROM OWNER

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ9867E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	XU XUPING
Contact Number	(Phone) +65-82228167
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBK5633J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	PANNEER MURUGANANTHAN
Contact Number	(Phone) +65-83164250
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Sketch Plan


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



Describe Circumstances of the Accident

JLR 101 E

5/10/2022

Presented here with a letter from a nurse informing me that on 4/6/2022 at 2.30pm when driving northwards A1112 closing CR 101 (SS) 10/11/2022 as a result of a collision with a car on the right side of the road.

My car was not at reporting center for photo taking.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	741Z
Vehicle Details	
Vehicle No.:	SLR101E
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200D SE
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	65492080107461
Chassis No.:	WDD2130132A242082
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$43,382.00
Original Registration Date:	12 Oct 2017
First Registration Date:	12 Oct 2017
Transfer Count:	1
Actual ARF Paid:	\$37,735.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Oct 2027
PARF Rebate Amount:	\$26,414.00
Intended COE Rebate Details	
COE Expiry Date:	11 Oct 2027
COE Category:	E+ Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,005.00
COE Rebate Amount:	\$23,202.00
Total Rebate Amount:	\$49,616.00

Mercedes-Benz GLE-Class GLE300d AMG Line 4MATIC Premium Plus 7-Seater

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREM

Price	\$398,800		
Depreciation	\$35,560 /yr View models with similar depre	Reg Date	20-Jul-2022 (9yrs 7mths 8days COE left)
Mileage	1,300 km	Manufactured	2021
Road Tax	\$1,734 /yr	Transmission	Auto
Dereg Value	\$171,258 as of today (change)	Fuel Type	Diesel (Euro 5 Engine and Above)
COE	\$110,524	OMV	\$78,957
Engine Cap	1,950 cc	ARF	\$114,123
Curb Weight	2,165 kg	Power	180.0 kW (241 bhp)
Type of Vehicle	SUV	No. of Owners	1



Car comes with 6-mth Sgcarmart W

