

ASS. REC. BY:

REF:

CS/CT 12702799/Tups

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Bal. or Market Value: \$54K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SLR 71494Yr Regn: 2017Aug

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi

c.c

1193Colour: white

A/C:

Insured / Std / NI / NA

Sp. Reading: 59505

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MMBSTA13AH4-00544

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 185/55R15R: 185/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. _____

D.O.I. 9/12/22Survey held at Kilpost

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

S + RS. \$ _____

☐

: Interview (\$ _____)

Photos

☐

: Tech. Invs (\$ _____)

Others

☐

: Weekend (\$ _____)

TOTAL

TOTAL

Rep. Format: _____

Lump Sum / L.S.I. (\$) _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	723Z
Vehicle Details	
Vehicle No.:	SLR7149Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Dec 2022
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	3A92UGA6992
Chassis No.:	MMBSTA13AHH005494
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$12,720.00
Original Registration Date:	25 Aug 2017
First Registration Date:	25 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Aug 2027
PARF Rebate Amount:	\$3,500.00
Intended COE Rebate Details	
COE Expiry Date:	24 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$20,169.00
Total Rebate Amount:	\$23,669.00

The information contained herein is correct as at 06 Dec 2022

OK

Date of Accident : 06 Dec 2022 Accident Time: 1335 (24-HR-FORMAT)
Accident Place : Slip Road of YK towards Hongan Ave 3.
Vehicle Reg. No (Car plate No.) : SLK 71494 CC: 102 Vehicle Make/Model: Mit Attrage
Insurance Company : MTUC Policy No.:
Name of Registered Owner : Company / Individual Koh Cheng Neo Cecilia
ID of Registered Owner : Co Reg No: Owner's NRIC No: S13587032
OWNER EMAIL ADDRESS: : Co Contact No: Owner's Contact No: 9625 8979
cecilia.koh@live.com

DRIVER'S Name : DRIVER'S NRIC No:
DRIVER'S Date of Birth : 21 Nov 1958 DRIVER'S License Pass Date 18 Dec 1982
Relationship bet. Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: self.
DRIVER'S Address : Block 406 Hongan Ave 10 #08-1132 S(530406)
DRIVER'S Contact No./ Alt No. : 1) 2)
DRIVER'S Occupation : INDOOR \ OUTDOOR (eg. working inside or outside of an ofc)
Email Address :
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance

Number of Passengers (including Driver): 1 Name & Gender: Male.
Was the accident reported to the police? YES \ NO
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any injuries, if yes (name of the injured person)

Other Party Driver's Particulars (if any)

Vehicle Reg No: <u>G6K7833K</u>	Vehicle Reg No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name DRIVER: _____	Name DRIVER: _____
IC No. DRIVER: _____	IC No. DRIVER: _____
DRIVER'S Contact & add: _____	DRIVER'S Contact & add: _____

REPORT FORM EXPLAINED IN : ENGLISH / CHINESE / MALAY / TAMIL OTHERS: _____

WHO REPORTED THE ACCIDENT : OWNER / DRIVER / BOTH

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

calis
Policyholder's Signature / Date & Time

calis
Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

I was travelling at the Slip road of KK towards
Hongkong Ave 2. I was stationary behind the stop
line going away to the vehicle at the major road.
Out of sudden, I felt an impact from my vehicle
rear portion. When I got down, I saw vehicle (B)
collided onto me.

Declaration

I/We declare the foregoing particulars are true in every respect.

actis

Policyholder's Signature / Date & Time

actis

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SLR7149Y

Make & Model: Mitsubishi Attrage

Chassis number: MMBSTA13AHH005494

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bootlid	1	\$ 858.00
2	Bootlid centre emblem	1	\$ 53.00
3	Bootlid "Attrage" emblem	1	\$ 21.00
4	Bootlid "MIVEC" emblem	1	\$ 43.00
5	Bootlid chrome moulding	1	\$ 318.00
6	Bootlid chrome moulding clips	1set	\$ 50.00
7	Bootlid RH hinge	1	\$ 192.00
8	Bootlid LH hinge	1	\$ 192.00
9	Bootlid lock	1	\$ 208.00
10	Bootlid lock catch	1	\$ 68.00
11	Bootlid weatherstrip	1	\$ 178.00
12	Rear bumper	1	\$ 654.00
13	Rear bumper clips	1set	\$ 60.00
14	Rear bumper RH retainer	1	\$ 32.00
15	Rear bumper LH retainer	1	\$ 32.00
16	Rear bumper LH reflector	1	\$ 41.00
17	Rear bumper RH reflector	1	\$ 41.00
18	LH taillamp assy	1	\$ 402.00
19	LH taillamp panel	1	\$ 98.00
20	LH taillamp lock clips	1set	\$ 22.00
21	RH taillamp assy	1	\$ 402.00
22	RH taillamp panel	1	\$ 98.00
23	RH taillamp lock clips	1set	\$ 22.00
24	End panel	1	\$ 455.00
25	End panel inner garnish	1	\$ 89.00
26	End panel inner garnish clips	1set	\$ 60.00
27	End panel air vent	1	\$ 39.00
28	End panel air vent cover	1	\$ 53.00
29	End panel RH side cover	1	\$ 28.00
30	End panel antenna sensor	1	\$ 101.00
31	End panel buzzer sensor	1	\$ 95.00
32	LH rear fender	1	\$ 808.00
33	LH rear fender inner trim board	1	\$ 233.00
34	LH rear fender inner trim board clips	1set	\$ 45.00
35	LH rear fender splash shield	1	\$ 55.00
36	LH rear fender splash shield clips	1set	\$ 30.00
37	RH rear fender	1	\$ 808.00
38	RH rear fender inner trim board	1	\$ 233.00
39	RH rear fender inner trim board clips	1set	\$ 45.00

40	RH rear fender splash shield	1	\$	55.00
41	RH rear fender splash shield clips	1set	\$	30.00
42	Spare tyre panel	1	\$	923.00
43	Spare tyre panel mat	1	\$	198.00
44	Spare tyre panel top cover	1	\$	339.00
45	Spare tyre panel insulator	1	\$	187.00
46	Exhaust silencer	1	\$	598.00
47	Exhaust silencer gasket	1	\$	36.00
48	Exhaust silencer hangers	1	\$	67.00
			\$	9,695.00
		Parts less 10%	\$	969.50
		Total	\$	8,725.50

No.	Special Nett Items		Amount S\$
1	Bootlid "C&C" emblem	1	\$ 85.00
2	Bootlid seal	1	\$ 60.00
3	End panel joint sealant	1	\$ 70.00
4	Spare tyre panel joint sealant	1	\$ 80.00
5	Rear bumper reverse sensor	1set	\$ 320.00
6	Rear reverse camera	1	\$ 780.00
7	Rear number plate	1	\$ 70.00
8	Rear windscreen glass sealant	1	\$ 70.00
9	Rear windscreen glass inner seal	1	\$ 50.00
10	RH taillamp panel joint sealant	1	\$ 40.00
11	LH taillamp panel joint sealant	1	\$ 40.00
		Total:	\$ 1,665.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 2,400.00
2	Spray painting on affected areas and panels	\$ 2,000.00
3	Check wiring and lighting system on affected areas	\$ 100.00
4	Apply rust coating chemical on affected areas and panels	\$ 100.00
5	Remove and replace rear bumper reverse sensors to assist repair	\$ 100.00
6	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 350.00
7	Remove and replace exhaust silencer and hangers to assist repair	\$ 180.00

8	Remove and replace rear reverse camera to assist repair	\$ 120.00	X
9	Remove and reinstall roof lining, seats and carpet to assist repair	\$ 480.00	X
10	Mount vehicle on chassis alignment bench to repair chassis frames	\$ 650.00	X
11	Remove and reinstall fuel tank, pipes, hoses and sensors to assist repair	\$ 220.00	X

Total: \$ 6,700.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 8,725.50

Special Nett: \$ 1,665.00

Labour: \$ 6,700.00

Total Amount: \$ 17,090.50

Tanfer 9749 5749
 WP 9/12/22 @ 445
 c/s resurvey after repair
 transfer @ 11 hours - 6 days

- To check consistency of accident
- To check part prices

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer