



Service Request Details

Claim

S2M04FWO

Reference

CS3/ASM22012308/Tvp3 

Loss Date

2 December 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

5 Dec 2022 10:24:05 AM

Request Date

8 December 2022

Due Date

8 December 2023

Services

Pre-Repair Survey

Actions

Next Step

Finish the work

Complete Work



Insured

COMFORT TRANSPORTATION PTE LTD 383 SIN MING DRIVE, 575717, Singapore 65551188

Vehicle Information

Incident Vehicle Registration #
FBQ5000D

Make
TPVD YAMAHA

Model
NMAX

Service Address

, , ,

Primary Contact

SOH SANDY ANNE (SU SANDY ANNE
Singapore
91804947

Claim Handler

LOH Cynthia

cynthia.loh@axa.com.sg

Additional Instructions

Messages1	Invoices	History	Documents	Assessment	Metrics	Notes
-----------	----------	---------	-----------	------------	---------	-------

TYPE



SENT

8/12/22 6:02 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

Assignment

BODY

Dear Cynthia, thank you for the assignment.

