

ASS. REC. BY: NA 2

REF:

III

Ju L13

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 9408G Yr Regn: 2 APR 2019Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or _____

Make: HYUNDAI IONIA G2 c.c. 1,580Colour: BLUE A/C: (Insured) Std / NI / NASp. Reading: 443,196 T/Radio: (Insured) Std / NI / NA

Eng/No: _____

C/No: KMHCB851ZUKU141569Gen. Cond: Good / (Fair) / Poor / BurntSteering: (Inorder) / Jammed / Leaked / Burnt orBrake: (Inorder) / Jammed / Leaked / Burnt orModl: NI / S/Rim / (STD) A/Rim orTyre Size: F: 195/65R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTAKE

Front

Rear

R/Bal. 6 mmR/Bal. 5 mmL/Bal. 6 mmL/Bal. 5 mmD.O.A. 6/12/2022D.O.I. 8/12/2022Survey held at CDGE LOYANGDes. of Damages: (Frt) / Rear / O/S / N/S / U/C / Rooftop orO/S FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

III L13

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS _____ SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)