

Our Job Ref No : 305538859

Date 10.12.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. SH 9408G

Date of Accident : 06.12.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill 703A INDIA --- SMV6258P
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,850.00
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : 

Name : NAZ

Date : 15/12/2022

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	----	NO		
3. Survey Fees	----	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: India International Insurance Pte Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/12/2022
Vehicle Reg. No.:	SH9408G	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	02/04/2019
Vehicle Colour:	BLUE		
Engine No:	G4LEJU192066	Chassis No:	KMHC851CVKU141569
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	2,073.12
Miscellaneous Items	11.00
Labour	750.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,834.12
+ GST 7.00% (S\$)	198.39
Nett Amount (S\$)	3,032.51

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2022)
Parts: 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SH9408G/07/12/2022 08:25	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY	20.00	0.00	*481.10 FLXR
2	1		*HEADLAMP ASSY RH	20.00	0.00	*2,110.30 FL/SQ
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)						2,591.40
- List Item Discount on L Items (\$\$)						518.28
Total Parts (\$\$)						2,073.12

ComfortDelGro Engineering Pte Ltd/SH9408G/07/12/2022 08:25. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	400.00	350
2	SPRAYPAINT	New	300.00	250
3	CHECK WIRING	New	50.00	30
Gross Labour Cost (S\$)			750.00	

ComfortDelGro Engineering Pte Ltd/SH9408G/07/12/2022 08:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NA2 LKK

8/12/2022 1655

LIS \$1850.00

2 DAYS

AFTER REPAIR PHOTOS

LKK Acknowledged by Repairer to notify the Policyholder of the following:

- To inform the Policyholder of the estimated repair cost
- To inform the Policyholder of the estimated repair time
- To inform the Policyholder of the estimated repair location
- To inform the Policyholder of the estimated repair date
- To inform the Policyholder of the estimated repair time
- To inform the Policyholder of the estimated repair location
- To inform the Policyholder of the estimated repair date
- To inform the Policyholder of the estimated repair time
- To inform the Policyholder of the estimated repair location
- To inform the Policyholder of the estimated repair date

Acknowledged by Repairer
Signature:
Date: