

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / T / P / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBT 66936

at Workshop n/s M1 MOTORING

of 48, TOTTENHAM RD EAST

Insured: ASM

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

22k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 12k

ESTIMATE RANGE OF REPAIR / no of days - (2k-3k) / 3 days

Veh No:

FBT 66936

Yr Regn:

2022 APR

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA XMAX 300 ABS CVT cc 292

Colour:

MULTI

A/C: Insured / Std / NI / NA

Sp. Reading

23828

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

M43SH18211015907

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / 5 Rim / STD A/Rim or

Tyre Size:

F:

120/70-15

R:

140/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

06/12/22

D.O.I.

12/12/22

Survey held at

M1 MOTORING

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S Fnt

The U/C / Chassis Frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS. SI

) Photos

) Others

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 929Z

Vehicle Details

Vehicle No.: FBT6693G

Vehicle to be Exported: No

Intended Deregistration Date: 13 Dec 2022

Vehicle Make: YAMAHA

Vehicle Model: XMAX 300 ABS CVT

Primary Colour: Red

Manufacturing Year: 2021

Engine No.: H345E0023625

Chassis No.: MH3SH182111015907

Maximum Power Output: -

Open Market Value: \$6,262.00

Original Registration Date: 22 Apr 2022

First Registration Date: 22 Apr 2022

Transfer Count: 1

Actual ARF Paid: \$1,381.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 21 Apr 2032

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$10,501.00

COE Rebate Amount: \$9,824.00

Total Rebate Amount: \$9,824.00

Yamaha Xmax 300

Listing Type

Paid Ad

Brand

Yamaha

Model

Yamaha Xmax 300

Engine Capacity

292cc

Classification

Class 2A

Registration Date

21/07/2021

COE Expiry Date

20/07/2031

(8yrs 7mths 7days COE left)

Mileage

-

No. of owners

-

Type of Vehicle

Scooters

SGD \$20900