

(08/11/11) Wed

ASS. REC. BY: John

REF:

CS3/ASM22012343/Rvp3

1966

COC-2025/may

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / T / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFV 85392at Workshop n/s CAR HUB HOLDINGSof 143, BUNNET TIMAH RD

Insured:

ASM

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

28K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR UNIT - 9K

ESTIMATE RANGE OF REPAIR / no. of days - (4K-5K / 6 days)

Veh No:

SFV 85392

Yr Regn:

2005 / Jun

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

TOYOTA COROLLA ALTIS

cc 1598

Colour:

GREY

A/C:

Insured / Std / NI / NA

Sp. Reading:

218147

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053ZEC107090056

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ STD / ☐ Rim or

Tyre Size:

F:

185/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

08/12/22

D.O.I.

12/12/22

Survey held at

CAR HUB

Des. of Damages: Frt / Rear / ☒ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



Preli. Report

1)

Date/Time, File Return to?



Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$