

ASS. REC. BY: TayphREF: 3/17/22012355 Hups**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s. _____

of _____

Insured: **GBC 2743L**Policy No. **DMCVSNA00078882201**Claims No. **SNM22D208385/C02/TAYHP**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 987K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMV 4700S Yr Regn: 2020 1 Sep

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Seat Toledo c.c. 1395Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 50574 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSS777NH ZK 10/1872

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 19/11/2022D.O.I. 7/12/22Survey held at Bifrost

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/6/23 Lump Sum \$6900 confirmed by email (Red 13,104.59, 65%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 19/6/23-typist

Report Format: **Merimen**Lump Sum / L&L: **\$6900**Days Of Repair: **6**

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 906C

Vehicle Details

Vehicle No.: SMV4700S
Vehicle to be Exported: Yes
Intended Deregistration Date: 23 Nov 2022
Vehicle Make: SEAT
Vehicle Model: TOLEDO 1.4 TSI 125 STYLE 7AT
Primary Colour: Grey
Manufacturing Year: 2019
Engine No.: CZCA15734
Chassis No.: VSSZZZNHZK1011872
Maximum Power Output: 92.0 kW (123 bhp)
Open Market Value: \$19,256.00
Original Registration Date: 30 Sep 2020
First Registration Date: 30 Sep 2020
Transfer Count: 0
Actual ARF Paid: \$9,256.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Sep 2030
PARF Rebate Amount: \$6,942.00

Intended COE Rebate Details

COE Expiry Date: 29 Sep 2030
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$38,504.00
COE Rebate Amount: \$30,225.00
Total Rebate Amount: \$37,167.00

The information contained herein is correct as at 22 Nov 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/11/2022 16:28 (SGT)
Reported by	Driver
Date of Accident	19/11/2022 07:55 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	TOWARDS CHANGI EXIT EUNOS
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMV4700S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHEN JUNJIE
NRIC No	S8241906C
Email Address	LIZCHEN@GMAIL.COM
Mobile Phone No	(Phone) +65-94789152
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Seat
Model	Toledo
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1400

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number	MT/01089662

DRIVER

Name of Driver	HON JIA KAI JUSTIN
NRIC No	S8530506I
Date Of Birth	10/09/1985
Occupation	Indoor

Date Of Driving Pass	18/05/2005
Driving experience	17 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-80116003
Alt. Phone Number	-
Email Address	HJKJUSTIN@GMAIL.COM
Address	267 BOON LAY DRIVE #13-749
Address complement	-
Postcode	640267
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED
STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2743L
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-

Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	HON JIA KAI JUSTIN
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SMV4700S
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



A. SMV4700S
B. GBC2743L

1

Describe Circumstance of the Accident

I travel from PIG Changi to Eunos Ext.
when I stop at the traffic light. Behind Lorry
lost control and hit my rear left bumper.

Declaration

I/We declare the foregoing particulars are true in every respect.

If you wish to claim against your own policy, please be advised that your insurer may have a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence. Kindly check with your insurer for more details.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

VDE OFF

BHEENR

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SMV4700S

Make & Model: SEAT Toledo

Chassis number: VSSZZZNHZK1011872

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bootlid	1	\$ 184 1,811.40
2	Bootlid centre emblem	1	\$ new 113.00
3	Bootlid "Toledo" emblem	1	\$ new 133.50
4	Bootlid LH lamp	1	\$ new 505.20
5	Rear bumper	1	\$ de 1,584.70
6	Rear bumper RH side retainer	1	\$ X 85.30
7	Rear bumper LH side retainer	1	\$ de 85.30
8	Rear bumper LH reverse sensor	1	\$ new 303.60
9	Rear bumper reverse sensor rubber seal	2	\$ new 15.00
10	Rear bumper reverse sensor holders	2	\$ new 64.00
11	LH taillamp assy	1	\$ new 596.70
12	LH taillamp panel	1	\$ Ry 194.20
13	LH taillamp lock clips	1set	\$ X 43.00
14	End panel	1	\$ 66 686.70
15	End panel inner garnish	1	\$ X 231.50
16	Rear windscreen glass with rubber moulding	1	\$ X 1,302.80
17	Rear LH fender	1	\$ bu 1,886.90
18	Rear LH fender splash shield	1	\$ X 95.40
19	Rear LH fender inner trim board	1	\$ X 552.10
20	Rear LH fender inner lower air duct	1	\$ X 93.20
21	Rear LH sport rim	1	\$ X 787.90
22	Rear LH wheel bearing	1	\$ X 623.70
23	Rear LH door	1	\$ X 1,755.30
24	Rear LH door weatherstrip	1	\$ X 231.40
25	Rear LH door lock	1	\$ X 590.60
26	Rear LH door inner trim board	1	\$ X 1,045.30

Rear bumper sponge ~~de~~

Parts less 10% \$ 15,417.70
 Total \$ 1,541.77
 Total \$ 13,875.93

No.	Special Nett Items	Qty	Amount S\$
1	Rear bumper clips	1set	\$ 30w 80.00
2	Rear bumper clips	1set	\$ X 80.00

3	LH taillamp panel joint seal	1	\$ X 67	50.00
4	End panel joint sealant	1	\$ 400	80.00
5	End panel inner garnish clips	1	\$ X 60	60.00
6	Rear windscreen glass sealant	1	\$ X 80	80.00
7	Rear windscreen glass inner seal	1	\$ X 60	60.00
8	Rear LH fender joint sealant	1	\$ 400	100.00
9	Rear LH fender splash shield clips	1set	\$ X 70	70.00
10	Rear LH fender inner trim board clips	1set	\$ X 70	70.00

Total: \$ 730.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 800 1,600.00
2	Spray painting on affected areas and panels	\$ 900 1,400.00
3	Check wiring and lighting system on affected areas	\$ 50 80.00
4	Spray rust chemical coating on repaired and replaced panels	\$ 50 100.00
5	Remove and replace rear windscreen glass to assist repair	\$ X 220.00
6	Remove and reinstall roof lining, seats and carpet to assist repair	60 \$ 450.00
7	Remove and replace rear LH door inner mechanism to new door	\$ X 150.00
8	Test drive and adjust wheel alignment system	\$ X 180.00
9	Remove and replace rear undercarriage parts to assist repair	\$ X 550.00
10	Remove and replace rear bumper reverse sensors to assist repair	\$ 30 100.00
11	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 60 400.00

Total: \$ 5,230.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 13,875.93
Special Nett: \$ 730.00
Labour: \$ 5,230.00

Total Amount: \$ 19,835.93

Tan Kah 9749544
WP 7/12/22 @ 1130
L/S Resurvey after repair
Tan Kah C/Chanto.com
6 days

- To check consistency of accident
- To check part prices

LK Consultants hence notify the insurer of the following:

- To resurvey before/after spray painting
- To document damaged part(s) during resurvey
- Parts are subject to confirmation
- This survey is on a "Without Prejudice" basis
- No communication(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Supplementary Estimate

Vehicle number: SMV4700S

Make & Model: Seat Toledo

Chassis number:

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Rear bumper inner sponge	1	\$ <i>de</i> 187.40

2/10/12
9/12

\$ 187.40
Parts less 10% \$ 18.74
Total \$ 168.66

No.	Special Nett Items	Qty	Amount S\$

Total: \$ -

No.	Labour and painting	Amount S\$

Total: \$ -

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 168.66
Special Nett: \$ -
Labour: \$ -