

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	INSURANCE (S) PL	Re	ef:	CS/AGI22012379/Uny3e2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	30/12/2022	
			Co	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLE 8632E	Veh. Inspected		SKA 9925L	
	Policy No.	P10194542R03	Coverage (\$)		0.00	
	Claim No.	C10019159 /JT	Excess (\$)		0.00	
	Assign From	FRAULEINE KHOO	Assign Date		09/12/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	VOLKSWAGEN SCIROCCO 1.4 (A)	c.c		1390	
	Engine No.	HIDDEN	Year of Reg.		2011	
	Chassis No.	WVWZZZ13ZBV026760	Colour		BLACK	
	Odometer	248378 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	245/40 R18	GOODYEAR		6 mm	
	L/H Front Tyre	245/40 R18	GOODYEAR		6 mm	
	R/H Rear Tyre	245/40 R18	HANKOOK		6 mm	
	L/H Rear Tyre	245/40 R18	HANKOOK		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	08/12/2022	Inspection Date		09/12/2022	
	Survey held at	FASTECH AUTO PTE LTD				
	1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: