ASS. REC. BY: Tauff Veh No: \$40 8685 Yr Regn: 2017 1200. Date: From: Type: M.Car / M.Cycle / Bus / Van / Lorry /: Taxi / Prime Mover / Estimated Cost: .Truck / Trailer or OD / TP/I WS / TP RES / OD RES / EVA / INV / MV Vol lisnegren Sheren. Make: To Inspect Vehicle No: Insured / Std / NI / NA Colour at Workshop m/s T/Radio: Insured / Std / NI / NA Sò.Reading Eng/No: Insured: WWW EZZ TNZMVZS C/No: Policy No. Gen. Cond: Good / Fair / Poor / Burnt Claims No. Steering: Inorder Jammed / Leaked / Burnt or Excess: Sum Insured: Brake: Inorder / Jammed / Leakad / Burnt or (Client's Record) Modi: Nil / S/Rim / STD A/Rim or Make of Veh: Tyre Size: (Policy Condition) BS / DUN / EXNOVA / GY /-FS / LIZA MC / OHTSU / PIR / SUMI / Remark: The veh had commenced its N/S OIS repair at the time of inspection. TOYO / YOKO or \$90K Rear Front Bal. or Market Value: R/Bal. R/Bal. Consistent?: Yes or No IDAC Accident Rport: L/Bal. ∐Bal. Consistent?: Yes or No GIA / PR Seen: D.O.I. days Res.: Yes or No D.O.A. Est. Repairs: 3 Val.: Yes or No Survey held at Lum Sum: Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Fut NIS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: Date / Time | Action / Instruction Date/Time, File Pass to? Days Of Repair: : Preli. Report Survey Fee: Resurvey No. of Trip: : Final Report Transportation: Date/Time, File Return to? Add Fee: S + RS.__SI : Site Insp (\$: Interview (\$ Photos Tech, Invs (\$ Reperformat: Lump Sum / LB.A: C: : Weel:end (\$ TOTAL

Cs. (1122012394 TUPS

> Back to OneMotoring

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	727F
Vehicle No.:	SGD8688J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Dec 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SHARAN 2.0 TSI 7N24MY
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	DED012455
Chassis No.:	WVWZZZ7NZHV236734
Maximum Power Output:	162.0 kW (217 bhp)
Open Market Value:	\$34,825.00
Original Registration Date:	30 Jun 2017
First Registration Date:	30 Jun 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$40,755.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2027
PARF Rebate Amount: Intended COE Rebate Details	\$28,528.00
COE Expiry Date:	29 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,414.00
COE Rebate Amount:	\$25,228.00
Total Rebate Amount:	\$53,756.00

The information contained herein is correct as at 09 Dec 2022

DATE OF ACCIDENT	MAKE & MODEL: VL SHAPPAN. AUTO/MANUA			
TIME OF ACCIDENT	08/12/22. CC 20.			
LOCATION OF ACCIDENT	(800 AM/PM)			
EXACT PURPOSE USED AT TIME OF ACCID	TAI KENG LANE.			
NAME OF OWNER	- THEVALE OSE / PRIVATE HIRE			
	PETER MILTON SIVIATHASIAN.			
NRIC PETERMILTON . S & G	mpil. 40- OFFICE: MOBILE: 90 488 68			
	S7438727F			
CLAIM TYPE	OD / THIRTY PARTY / REPORTING ONLY			
FLEET POLICY	TACHERING CO. YES / NO?			
	CN TAIPING.			
TYPE OF COVERAGE	Comprehensive / Third Party / Third Party Fire & Theft			
POLICYNO.	Pm&CSNW00119682202.			
NAME OF DRIVER	AS ABOVE / IF NO: 1			
NRIC	Č1			
DATE OF BIRTH	20 / 11 / 74.			
ANY PASSENGER	YES /NO: PRIVEYLONGS.			
NAME OF PASSENGER	- PIETO MASACA.			
GENDER OF PASSENGER	MALE / FEMALE			
OCCUPATION	Outdoor /indoor			
DATE OF DRIVING PASS	15.105 / 98.			
GENDER	MALE / FEMALE			
CONTACT NO.	35.1.1.0			
EMAIL	PETERMICTON . S C GMAIL .Com			
ADDRESS	175 Tay Keys Garalt Con			
DOES DRIVER OWN OTHER VEHICLES?	NO/If yes, Reg No: INSURE: -			
RELATIONSHIP	Employee / If No: SCIF.			
WEATHER CONDITION	Clear / Raining / Other:			
ROAD SURFACE	Dry / Wet JOther:			
ANY INJURIES	No! If yes, Who?			
CONTACT NO.				
ROLICE REPORT	(No / If yes, Where?			
NOTICE OF INTENDED PROSECUTION?	Nov/ If yes, Who?			
VEHICLE B NO.	SLS 800 12. Any Passenger: DRIVER ONLY			
NAME	DETUCTO SIVER			
CONTACT NO.				
VEHICLE C NO.	Any Passenger:			
VEHICLE D NO.	Any Passenger:			
VEHICLE E NO.	Any Passenger:			
VEHICLE F NO.	Any Passenger:			
ANY WITNESS WITNESS CONTACT NO.				
WAS THERE ANY VIDEO CAPTURE?	YES / NO			
WAS THERE ANY AUDIO RECORDED?	YES MO			
SCENE ACCIDENT PHOTOS TAKEN?	YES (NO.			
WHO IS REPORTING	DRIVER/OWNER/BOTH			
Original Language Used	English/ Mandarin/ Others:			
Tave you been approach by unknown person oliciting (s) / offering accident claims ssistance?	YES /NO-			

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facismay allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapora (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could invoive disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third-party service providers or agents (Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature Date & Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

Pa Van G Va

Describe Circumstance of the Accident
ON THE STATED PATE AND TIME, I WAS TRIAVELLIN
STRIAIGHT.
OUT OF NOWHERE, VEH B. ENGAGED HIS REVERSE
GEAR IAND REVERSED PARRUPTLY AT IA GREAT SPEED.
1 CHECKED MY REAP VICE MIRROL AMI SAL A
VEHICLE JEHIND ME AS SUCH I COULDN'T REVENESE TO
AVOR 1A GUISION. I HONICED REPENTEDLY BUT
VEH B STILL REVERSED AND THE DATE ME

Declaration

I/We declare the foregoing particulars are true in every respect.



BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457 Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SGD8688J Make & Model: Volkswagen Sharan Chassis number: WVWZZZ7NZHV236734

Date of survey: Name of surveyor: Contacts:

Parts less 10% \$

Total \$

1,493.16

13,438.41

No.	Description of spare parts	Qty	Amount S\$
1	Front bumper	1	\$ \$ 2,214.59
2	Front bumper LH side corner parking sensor	1	\$ nu / 190.18
3	Front bumper LH side parking sensor	1	\$ × 1 ×190.18
4	Front bumper LH centre parking sensor	1	\$ x hw1190.18
5	Front bumper parking sensor rubber seal	6	\$ × 22.35
6	Front bumper LH fog lamp	1	\$ cm 372.13
7	Front bumper LH fog lamp cover		\$ art 189.91
8	Front bumper centre grille	1	\$ × \ 221.54
9	Front bumper centre grille chrome moulding	1	\$ × \ \220.19
10	Front bumper reinforcement	1	\$ x -47734.58
11	Front bumper centre bracket	1	\$ 155.32
12	Front bumper RH side retainer	1	\$ x \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
13	Front bumper LH side retainer	1	\$ (31.35
14	Front bumper RH inner bracket	1	\$ X un 33.19
15	Front bumper LH inner bracket	1	\$ X Y 33.19
16	LH headlamp	1	\$ 84 2,669.12
17	LH headlamp nozzle cover	1	\$ wt 26.00
18	LH headlamp nozzle	1	\$ 04 235.66
	LH headlamp upper panel	1	\$ x n 53.39
	RH headlamp	1	\$ X N ~ 2,736.03
	Front grille	1	\$ CM 606.73
	Front grille emblem	1	\$ 24/ 115.42
23	Support panel	1	\$ 🛚 🖈 905.02
	Aircon condenser	1	\$ x 876.95
	Radiator assy	1	\$ \$ 783.37
	Front LH fender	1	\$ x 872.62
27	Front LH fender splash shield	1	\$ 🗴 🔾 221.03
			\$ 14,931.57

No. **Special Nett Items** Amount S\$ Qty Front bumper clips \$ 30 MU / 80.00 1set 2 Front grille clips \$ 20 ML / 60.00 1set 3 Radiator coolant \$ x n√ 80.00 Front LH fender splash shield clips \$ k ^^ 70.00 1set

Total:

\$

290.00

No.	Labour and painting		Amount S\$		
1	Labour charges to remove, check, replace and reinstall	\$		1,300.00	
	damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas				
2	Spray painting on affected areas and panels 250	\$		1,200.00	
3	Check wiring and lighting system on affected areas	\$	30	80.00	
4	Apply rust coating chemical on affected areas and panels	\$	×	70.00	
5	Refocus and adjusyt headlamps assy	\$	×	80.00	
6	Remove and replace aircon condenser, pipes and hoses to assist repair. To refill gas	\$	X	220.00	
7	Remove and replace radiator assy, hoses and fan assy to assist repair. To refill coolant	\$	X	280.00	
	Total:	\$		3.230.00	

Agreed Amount: (Part by Part / Lump sum) Working days:

Spare Parts: \$ 13,438.41 Special Nett: \$ 290.00 Labour: \$ 3,230.00

Total Amount: 16,958.41

Tanfilm 97495749

WP 13/12/2205pm

4/5 Resny after veporir

fanfilm @ luhando.com

To check consistioney of accident

To check part prices

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: