

ASS. REC. BY:

REF:

TV / 220123961Kv

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

EM

of

Insured: SNG 7241Y

Policy No. D20MFL0007747_01

Claims No. MFL2022D0011380

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

8125-135k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 EST NOT READY

22/5 @ 5298.40

CASH

(red 2378.98, 30%)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 24/5/23-typist

Report Format: TP

Lump Sum / I.B.I.: (\$ 5298.40)

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S - RS. SI

Fixing

Others

Veh No:

SNB 7799G

Yr Regn:

OP, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

Palisade

3470

Colour

A. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

36123

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHR381CMMU335695

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

245/50R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

5

mm

L/Bal.

8

mm

L/Bal.

5

mm

D.O.A.

3 / 12 / 22

D.O.I.

12 / 12 / 2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

618G

Vehicle Details

Vehicle No.:

SNB7799G

Vehicle to be Exported:

No

Intended Deregistration Date:

06 Dec 2022

Vehicle Make:

HYUNDAI

Vehicle Model:

LX2 PALISADE 3.5 AT SR

Primary Colour:

Black

Manufacturing Year:

2021

Engine No.:

G6DCMA675707

Chassis No.:

KMHR381CMMU335695

Maximum Power Output:

204.0 kW (273 bhp)

Open Market Value:

\$39,163.00

Original Registration Date:

15 Sep 2021

First Registration Date:

15 Sep 2021

Transfer Count:

0

Actual ARF Paid:

\$46,829.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

14 Sep 2031

PARF Rebate Amount:

\$35,121.00

Intended COE Rebate Details

COE Expiry Date:

14 Sep 2031

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$62,600.00

COE Rebate Amount:

\$54,914.00

Total Rebate Amount:

\$90,035.00

The information contained herein is correct as at 05 Dec 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	03/12/2022 10:34 (SGT)
Reported by	Both
Date of Accident	03/12/2022 08:15 (SGT)
Exact Location of Accident	Lor 6 Toa Payoh, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number **SNB7799G**

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	VERONICA LOW CHOON YEE
NRIC No	S7316618G
Email Address	veronicavass@gmail.com
Mobile Phone No	(Phone) +65-96169941
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	LX2 PALISADE 3.5 AT SR
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	3470

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number	MT/01077521

DRIVER

Name of Driver	STEPHEN VASS
NRIC No	S2712675H
Date Of Birth	08/12/1959
Occupation	Indoor

Date Of Driving Pass	17/02/2003
Driving experience	19 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90055000
Alt. Phone Number	-
Email Address	svass@idc.com
Address	13 MARSILING LANE #03-01
Address complement	-
Postcode	730013
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	Yes
Vehicle Registration Number of Other Vehicle Owned by Driver 1	FQ1639R
Insurance Company of Other Vehicle Owned by Driver 1	Direct Asia Insurance (Singapore) Pte Ltd
Vehicle Registration Number of Other Vehicle Owned by Driver 2	FBF8319Z
Insurance Company of Other Vehicle Owned by Driver 2	Direct Asia Insurance (Singapore) Pte Ltd

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 3/12/2022 AT ABOUT 0815HRS.I WAS DRIVING STRAIGHT ALONG LOR 6 TOA PAYOH TWDS PIE. WHEN SUDDENLY VEHICLE B WHO WAS COMING OUT FROM KIM KEAT LINK AND COLLIDED ONTO MY VEHICLE.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SNG7241Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-

Vehicle Category	Private car
Name of Driver	LEE WEE SENG
NRIC No	S0035756A
Contact Number	(Phone) +65-96787348
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



EM Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity
Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

*Not Authorized
Resurvey B4 paint*

ESTIMATE

Date : 12th Dec 2022

Mdm Veronica Low Choon Yee
Blk 13 Marsiling Lane #03-01
Singapore 730013

85298.40

Veh No : SNB 7799G
Make/Model : Hyundai Palisade
Chassis No : KMHR381CMMU335695
Date of Acc : 03.12.22
TP Veh No : SNG 7241Y

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Frt Door LH		
2	1 pc	Frt Door Frame Moulding LH		
3	1 pc	Frt Door Glass Outer Moulding		
4	1 pc	Frt Door Garnish		
5	1 pc	Frt Door Lower Garnish LH		
7	1 pc	Frt Door Weatherstrip		
8	1 pc	Centre Pillar LH		
9	1 pc	Rear Door Lower Hinge LH		
10	1 pc	Rear Door LH		
11	1 pc	Rear Door Weatherstrip LH		
12	1 pc	Rear Door Frame Moulding LH		
13	1 pc	Rear Door Glass Outer Moulding LH		
14	1 pc	Rear Door Garnish (Frt) LH		
15	1 pc	Rear Door Garnish (Back), LH		
16	1 pc	Rear Door Lower Garnish LH		
18	1 pc	Petrol Tank Panel		
19	1 pc	Rear Fender LH		

Less 20% : \$ 1,649.13
Parts Total : \$ 4,947.38

- Labour**
- To remove & rearrange electrical wirings, check lightings
 - To remove & replace upholstery, trim garnishes to facilitate repairs.
 - To remove, transfer frt & rear doors components to new doors.
 - To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.
 - Putty and respray painting on affected portions.
 - To reset/recalibrate door mechanism/sensor system.
 - Rust proofing on affected portions.

\$ 80.00
\$ 100.00
\$ 300.00
\$ 900.00
\$ 900.00
\$ 250.00
\$ 200.00
Labour Total : \$ 2,730.00

Total Parts & Labour : \$ 7,677.38

for EM Solution Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: