

CS3

REF:

AS M27 012408 / T9P3

AS: S. REC: BY: Tawf

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

933K

IDAC Accident Report _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBD6396Z

Yr Regn: 215 / Jan.

Type: M. Car / M. Cycle / Bus / Van / ☒ Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan Carstar

C.O. 2153

Colour Silver

A/C: Insured / Std / NI / NA

Sp. Reading _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SWISC27240856909

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modl: ☒ Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 195 / R15

R: 155 / R13 (07)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

Rear

R/Bal. 6 mm

R/Bal. 6/6 mm

L/Bal. 6 mm

L/Bal. 6/6 mm

D.O.A. _____

D.O.I. 13/12/27 0430pm

Survey held at Lam Auto

Des. of Damages: ☒ Fnt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Range: \$5000 - \$6000, 7 days.

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

Add Fee: ☐

: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. invs (\$ _____)



: Weekend (\$ _____)

Repair Formlet: _____

Lum Sum: \$12000