

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

China (Ysun)
Date: 07.12.2022
Time: 12:13:22
Page: 1
TH

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305538885
REGN NO : SHA3079D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.10.2019
DATE/TIME IN : 06.12.2022 16:20
ACCIDENT DATE : 06.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	XR
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	/CRA
0003 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	XNN
0004 04-01-0104-2544-G	CAP-RR HOOK	1	98.80	20.00	79.04	/DEF
0005 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	180.00	2.00-	180.00	XSVL

SUB-TOTAL : 1,005.16

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	50.00	30

SUB-TOTAL : 750.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305538885
REGN NO : SHA3079D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.10.2019
DATE/TIME IN : 06.12.2022 16:2
ACCIDENT DATE : 06.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,755.16

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

NAZ LKK

7/12/2022 1520
LIS

2 DAYS

AFTER REPAIR PHOTOS