

08/11/13, wef

ASS. REC. BY: Marcus

REF:

CS/ASM 2200 8948/Uny3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKW 4952A  
2nd Anln

at Workshop m/s

of

Insured:

SJT 6553H

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

645k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

9

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

f 287U  
Vehicle: IN / OUT  
LTA 23866

Veh No:

SKW 4952A

Yr Regn:

30/10/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

A71.4

Make:

Volkswagen Golf

c.c

1395

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

84285

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZAUZFW356402

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45 R 17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

10/09/22

D.O.I.

12/09/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear, O/S Rear &

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/9/22

have accident scene photo of folder  
with 22134 signed result of folder  
23/9/22 1/5 & 8400 in folder AH/100  
(Red, 18728, 68, 69%)

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1) 23/9/22

Date/Time, File Return to?

2)

Days Of Repair:

9

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 8400 )

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	12/09/2022 15:47 (SGT)
Reported by	Both
Date of Accident	10/09/2022 12:07 (SGT)
Exact Location of Accident	Lor 32 Geylang, Singapore
Additional Location Information	64A GEYLANG LOR 32 PARALLEL PARKING LOT
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW4952A
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	RUAMJAROENCHAI JUNYA
Passport No/FIN	GXXXX287U
Email Address	DOMINOKIT@GMAIL.COM
Mobile Phone No	(Phone) +65-93853730
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Golf
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1395

### INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5109407968-03

### DRIVER

Name of Driver	RUAMJAROENCHAI JUNYA
Passport No/FIN	GXXXX287U
Date Of Birth	07/12/1979
Occupation	Indoor

Date Of Driving Pass	04/05/2020
Driving experience	2 YEARS AND 4 MONTHS
Gender	Female
Mobile Number	(Phone) +65-93853730
Alt. Phone Number	-
Email Address	DOMINOKIT@GMAIL.COM
Address	46A GEYLANG LOR 32
Address complement	-
Postcode	398306
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN ATTACHED

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SJT6553A
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-

Address ..... -  
Address complement ..... -  
Postcode ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... -

#### WITNESS DETAILS

##### WITNESS 1

Name ..... FERIS  
Phone ..... (Phone) +65-98560144  
Email ..... -

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




*[Signature]* 12 Sep 22  
Policyholder's Signature / Date & Time

*[Signature]* 12 Sep 22  
Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

Sketch Plan




Describe Circumstance of the Accident



On the stated date and time, my vehicle was parked parallel stationary at the carpark lot of 46A Geylang Lor 32, as I just live nearby, I did hear a loud bang and was informed by my landlord that vehicle B has collided onto my stationary vehicle's rear left portion.

Declaration

I/We declare the foregoing particulars are true in every respect

 12 Sep 22  
Policyholder's Signature / Date & Time

 12 Sep 22  
Driver's Signature (if driver is not the policyholder) / Date & Time

   
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Foreign Identification Number
Owner ID:	287U
<b>Vehicle Details</b>	
Vehicle No.:	SKW4952A
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Sep 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF A7 1.4 TSI AT 5G13GZ W/O HID
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	CXS146680
Chassis No.:	WVWZZZAUZFW356402
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,158.00
Original Registration Date:	30 Oct 2015
First Registration Date:	30 Oct 2015
Transfer Count:	1
Actual ARF Paid:	\$9,158.00 4579
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2025
PARF Rebate Amount:	\$5,952.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,301.00
COE Rebate Amount:	\$17,914.00
<b>Total Rebate Amount:</b>	<b>\$23,866.00</b>

The information contained herein is correct as at 13 Sep 2022

OK



unfold greatness now

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$68 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Wish 1.8A, 100% Loan by GV CARS FINANCING



Secured Loan by In house  
finance, Warranty packages and  
services available.  
GV Automobile Centre *Starred*

Sort by   results/page

16 vehicles












golf 1.4

Any Category

Advanced Search



Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	golf 1.4	Any	Any	2015	Any	Any	Any	Available
	<b>Volkswagen Golf 1.4A TSI</b>	<b>\$51,500</b>	<b>\$15,460 /yr</b>	<b>25-Sep-2015</b>	<b>1,395 cc</b>	<b>129,000 km</b>	<b>Hatchback</b>	<b>Available</b>
1 owner, fully agent serviced w records, wear & tear done up, very well maintained exterior and interior condition! Flexible loan available...								
Posted: 10-Sep-2022								
	<b>Volkswagen Golf 1.4A TSI</b>	<b>\$50,500</b>	<b>\$14,690 /yr</b>	<b>28-Oct-2015</b>	<b>1,395 cc</b>	<b>139,000 km</b>	<b>Hatchback</b>	<b>Available</b>
2 owner, servicing just done, wear and tear done up. Taken care by previous owner, well maintained exterior and interior condition! Flexi...								
Posted: 10-Sep-2022								
	<b>Volkswagen Golf 1.4A TSI EQP Sunroof</b>	<b>\$49,800</b>	<b>\$14,510 /yr</b>	<b>28-Aug-2015</b>	<b>1,395 cc</b>	<b>109,000 km</b>	<b>Hatchback</b>	<b>Available</b>
Well kept condition, probably the most economical and spacious interior yet packed with amazing feature for a powerful zippy car servic...								
Posted: 09-Sep-2022								
	<b>Volkswagen Golf 1.4A TSI</b>	<b>\$48,000</b>	<b>\$13,270 /yr</b>	<b>21-Dec-2015</b>	<b>1,395 cc</b>	<b>-</b>	<b>Hatchback</b>	<b>Available</b>
Superb Condition, Well taken Care By Owner, Serviced Regularly, Engine / Gearbox Overhauled In May 2022, All Other Wear And Tear D...								
Posted: 08-Sep-2022								
	<b>Rear View Camera Integration For Volkswagen</b> Volkswagen Reverse Camera integration More info about this product							
	<b>Volkswagen Golf 1.4A TSI</b>	<b>\$47,800</b>	<b>\$14,190 /yr</b>	<b>30-Sep-2015</b>	<b>1,395 cc</b>	<b>-</b>	<b>Hatchback</b>	<b>Available</b>
Well Taken Care By Careful Owner. Pristine Condition. Black Interior Leather Seats. Spacious. Suitable For Daily Drive. Trade-in/Flexible L...								
Posted: 08-Sep-2022								
	<b>Volkswagen Golf 1.4A TSI</b>	<b>\$49,800</b>	<b>\$14,300 /yr</b>	<b>11-Nov-2015</b>	<b>1,395 cc</b>	<b>144,200 km</b>	<b>Hatchback</b>	<b>Available</b>
Well maintained unit! Don't miss! Bank or in house loan available. Call for more enquiries! We open mon to sat 10 am to 7 pm. Please ca...								
Posted: 06-Sep-2022								
	<b>Volkswagen Golf 1.4A TSI</b>	<b>\$46,500</b>	<b>\$14,180 /yr</b>	<b>28-Aug-2015</b>	<b>1,395 cc</b>	<b>129,000 km</b>	<b>Hatchback</b>	<b>Available</b>
Beautifully done up and well taken care of MK 7 Golf with \$15k worth of Accessories, wear and tear all done up with new battery, mounti...								
Posted: 05-Sep-2022								
	<b>Volkswagen Golf 1.4A TSI EQP</b>	<b>\$52,888</b>	<b>\$15,990 /yr</b>	<b>30-Jul-2015</b>	<b>1,395 cc</b>	<b>93,000 km</b>	<b>Hatchback</b>	<b>Available</b>



\* Submit to us

Not Allowed  
her  
12/09/22

1/5 # 8400  
9 days

SKW4952A Volkswagen Golf

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>Dis</i>	\$ 1171.20
2	2	Rear bumper bracket <i>11</i>	\$ 86.40 X
3	1	Rear bumper retainer <i>115 One</i>	\$ 89.60
4	1	Rear bumper reinforcement <i>11</i>	\$ 378.90 X
5	1	Rear bumper inner beam <i>11</i>	\$ 189.70 X
6	1	Rear bumper reflector <i>115 520</i>	\$ 360.20 <i>68.50</i>
7	1	Rear bumper tow cover <i>11</i>	\$ 88.00 X
8	1	Rear tailgate assy <i>R</i>	\$ 1,632.10 X
9	1	Rear tailgate centre logo <i>11</i>	\$ 128.50 X
10	1	Rear tailgate TSI emblem <i>11</i>	\$ 108.50 X
11	1	Rear tailgate bluemotion emblem <i>11</i>	\$ 120.80 X
12	1	Rear tailgate Golf emblem <i>11</i>	\$ 118.50 X
13	1	Rear tailgate lock mechanism <i>11</i>	\$ 180.30 X
14	1	Rear tailgate lock catch <i>11</i>	\$ 86.40 X
15	1	Rear tailgate weatherstrip <i>11</i>	\$ 183.10 X
16	1	Rear tailgate left taillamp <i>11</i>	\$ 445.20 X
17	1	Rear tailgate right taillamp <i>11</i>	\$ 445.20 X
18	1	Rear tailgate inner board <i>11</i>	\$ 378.60 X
19	1	Rear left fender assy <i>Body/Bul</i>	\$ 1466.40
20	1	Rear left fender inner cowl <i>Torn</i>	\$ 181.90
21	1	Rear right fender assy <i>11</i>	\$ 998.40 X
22	1	Rear right fender inner cowl <i>11</i>	\$ 181.90 X
23	1	Rear left taillamp <i>522</i>	\$ 698.20 <i>485</i>
24	1	Rear right taillamp <i>11</i>	\$ 698.20 X
25	1	Rear left taillamp bracket <i>11</i>	\$ 23.50 X
26	1	Rear right taillamp bracket <i>11</i>	\$ 23.50 X <i>10463.20</i>
27	1	Rear end lower panel <i>550</i>	\$ 956.60
28	1	Rear end lower panel top garnish <i>11</i>	\$ 128.10 X
29	1	Rear windscreen glass moulding <i>11</i>	\$ 289.10 X
30	2	Rear no plate lamp <i>11</i>	\$ 188.00 X
31	2	Rear air duct ventilator <i>11</i>	\$ 176.00 X
32	1	Rear bumper lower spoiler <i>2e</i>	\$ 598.70 <i>382.00</i>
33	1	Rear left lower side panel <i>R</i>	\$ 878.90 X
34	1	Rear left lower spring carrier <i>25</i>	\$ 585.60 X
35	1	Rear right lower spring carrier <i>25</i>	\$ 585.60 X
36	1	Rear left trailing link <i>7w1</i>	\$ 197.50
37	1	Rear right trailing link <i>11</i>	\$ 197.50 X
38	1	Rear left trailing arm <i>Bul</i>	\$ 227.90
39	1	Rear right trailing arm <i>Bul</i>	\$ 227.90
40	1	Rear left lower arm <i>Bul</i>	\$ 579.10 <i>400.80</i>
41	1	Rear right lower arm <i>11</i>	\$ 579.10 X <i>400.80</i>
42	1	Rear right knuckle arm <i>Bul</i>	\$ 649.70 <i>610.00</i>
43	1	Rear left knuckle arm <i>Bul</i>	\$ 649.70 <i>610.00</i>
44	1	Rear left shock absorber assy <i>7w1</i>	\$ 798.20 <i>292.00</i>
45	1	Rear right shock absorber assy <i>11</i>	\$ 798.20 X
46	1	Rear left wheel bearing <i>Daye</i>	\$ 255.30
47	1	Rear right wheel bearing <i>Daye</i>	\$ 255.30
Less 10%			\$

102

20265.20

18238.68

**SKW4952A Volkswagen Golf**

			<b>Estimated Parts Price</b>	
<b>No</b>	<b>Qty</b>	<b>Parts Description</b>		
		<u>Special Nett Items</u>		
1	<del>12</del> 1	Rear bumper clips <i>nee</i>	\$	50.00 ✓
2	6	Rear end lower panel top garnish clips <i>11</i>	\$	30.00 x
3	1	Rear end lower panel sealant <i>nee</i>	\$	120.00 <i>50</i>
4	6	Rear tailgate inner board clips <i>11</i>	\$	30.00 x
5	1 set	Rear bumper reverse sensor <i>11</i>	\$	800.00 x
6	1	Rear windscreen glass sealant <i>11</i>	\$	80.00 x
7	6	Rear left fender inner cowling clips <i>nee</i>	\$	30.00 ✓
8	6	Rear right fender inner cowling clips <i>11</i>	\$	30.00 x
9	1	Rear right fender sealant <i>11</i>	\$	100.00 x
10	1	Rear left fender sealant <i>11</i>	\$	100.00 x
11	1	Rear left lower side panel sealant <i>11</i>	\$	100.00 x
12	1	Rear left wheel rim <i>cut/wopel</i>	\$	950.00 <i>500</i>
13	1	Rear right wheel rim <i>cut/wopel</i>	\$	950.00 <i>500</i>
14	1	Rear left tyre <i>see</i>	\$	350.00 x
15	1	Rear right tyre <i>see</i>	\$	350.00 x
16	1	Rear left brake disc <i>11</i>	\$	250.00 x
17	1	Rear right brake disc <i>11</i>	\$	250.00 x
18	1	Rear no plate with garnish <i>11</i>	\$	80.00 x
19	12	Rear bumper lower spoiler clips <i>11</i>	\$	50.00 x
			\$	4,700.00
<b>Total parts</b>			\$	<b>22,247.48</b>

**SKW4952A Volkswagen Golf**

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,400.00 1200
2	To putty and spray painting rear portion.	\$ 1,400.00 1000
3	To check rear lighting and wiring.	\$ 50.00 20
4	To remove and install rear bootlid lock mechanism.	\$ 11 80.00 x
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 80
6	To apply anti rust proofing to rear affected area.	\$ 140.00 60
7	To remove and install rear bumper reverse sensor.	\$ 80.00 50
8	To balance both rear wheel rim.	\$ 80.00
9	To conduct wheel alignment	\$ 120.00 } 80
10	To remove and install rear right undercarriage parts.	\$ 350.00 120
11	To remove and install rear left undercarriage parts.	\$ 350.00 120
		\$
<b>Total labour :</b>		<b>\$</b>

**Total parts : \$ 22,247.48** 27128.68  
**Total labour : \$ 4,290.00**  
**Total repair cost : \$ 26,537.48**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed on is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

27471.30  
 102  
 6724.17  
 1130  
 2730  
 10584.17  
 282  
 8467