

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

SOMPO INSURANCE SINGAPORE PL  50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623  Code: SMO  1. Policy Particulars:- THIRD PARTY CLAIM  Insured Veh. FBR 6931E  Veh. Inspected SJP 8116U  Policy No.  Coverage (\$) 0.00  Claim No. CMTD2204544/THE Excess (\$) 0.00  Assign From GRACE TEO Assign Date 13/12/2022  2. Vehicle Particulars & Condition  Make & Model HYUNDAI AVANTE C.C 1591  Engine No. HIDDEN Year of Reg. 2009	39/Any3e2	
SINGAPORE LAND TOWERSINGAPORE 048623  Code: SMO  1. Policy Particulars: - THIRD PARTY CLAIM  Insured Veh. FBR 6931E Veh. Inspected SJP 8116U  Policy No. Coverage (\$) 0.00  Claim No. CMTD2204544/THE Excess (\$) 0.00  Assign From GRACE TEO Assign Date 13/12/2022  2. Vehicle Particulars & Condition  Make & Model HYUNDAI AVANTE c.c 1591		
1. Policy Particulars :- THIRD PARTY CLAIM  Insured Veh. FBR 6931E Veh. Inspected SJP 8116U  Policy No. Coverage (\$) 0.00  Claim No. CMTD2204544/THE Excess (\$) 0.00  Assign From GRACE TEO Assign Date 13/12/2022  2. Vehicle Particulars & Condition  Make & Model HYUNDAI AVANTE c.c 1591		
Insured Veh. FBR 6931E Veh. Inspected SJP 8116U  Policy No. Coverage (\$) 0.00  Claim No. CMTD2204544/THE Excess (\$) 0.00  Assign From GRACE TEO Assign Date 13/12/2022  Vehicle Particulars & Condition  Make & Model HYUNDAI AVANTE c.c 1591		
Policy No.  Claim No.  CMTD2204544/THE  Excess (\$)  Assign From  GRACE TEO  Assign Date  13/12/2022  Vehicle Particulars & Condition  Make & Model HYUNDAI AVANTE  c.c  1591		
Claim No. CMTD2204544/THE Excess (\$) 0.00 Assign From GRACE TEO Assign Date 13/12/2022  Vehicle Particulars & Condition Make & Model HYUNDAI AVANTE c.c 1591		
Assign From GRACE TEO Assign Date 13/12/2022  2. Vehicle Particulars & Condition  Make & Model HYUNDAI AVANTE c.c 1591		
Vehicle Particulars & Condition  Make & Model HYUNDAI AVANTE c.c 1591		
Make & Model HYUNDAI AVANTE c.c 1591		
	2. Vehicle Particulars & Condition	
Engine No. HIDDEN Year of Box 2000		
Engine No. HIDDEN Year of Reg. 2009		
Chassis No. KMHDU41BR9U727634 Colour WHITE		
Odometer 337060 KM Steering IN ORDER		
Brakes IN ORDER Modification SPORTS RIM		
General GOOD		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre         185/65 R15         DUNLOP         6 mm		
L/H Front Tyre 185/65 R15 DUNLOP 6 mm		
R/H Rear Tyre 185/65 R15 DUNLOP 6 mm		
L/H Rear Tyre 185/65 R15 DUNLOP 6 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.		
DAMAGES SEE DETAILS.		
5. General Information		
Accident Date 12/12/2022 Inspection Date 13/12/2022		
Survey held at SPEEDWERKZ PTE LTD		
13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807		
5a. Remarks		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days		