

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



		AUTOMOBILE INSI	LOTI	ON KLFOKI		
INCC	ME INSURANCE	LTD	Ref:	NS/INC22012444/Nwp3e2		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	22-12-2022		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMH 6782R	Veh. Ir	nspected	SHD 7134K	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1201666-001	Exces	( )	0.00	
	Assign From		Assig	n Date	12/12/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMHU096286	Colou	r	BLUE	
	Odometer	539490	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	GITI		5 mm	
	L/H Front Tyre	205/60 R16	GITI		5 mm	
	R/H Rear Tyre	205/60 R16	GITI		5 mm	
	L/H Rear Tyre	205/60 R16	GITI		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	08/12/2022	Inspec	tion Date	12/12/2022	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					
	•					