

Date/Time: 12.12.2022 12:21 Page : 1

Job: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5399952

JC NO.305539339


OWNER	REGN NO. SHD7134K	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE HYUNDAI	FUEL
OMER NO. 7010045	MODEL I-40	E.....1/2.....F
ADDRESS 383 SIN MING DRIVE	DATE/TIME IN 12.12.2022 12:00	
Singapore SINGAPORE 575717	YR OF MANU. 10.11.2016	TARGET DATE
65508755 (R) (O)	CHASSIS CODE KMHLB41UMHU096286	COMPLETION DATE/TIME:
(P)		
JOB CARD NO.		

Accident Date: 08.12.2022
NATURE: 3P.08.12.22

JOB DESCRIPTION

NO	LABOR CODE
00050	PB
00060	SP
00070	20-00
00080	17-01

DESCRIPTION
PANEL BEATING
SPRAYPAINT CHARGE
TUFF COAT ON AFFECTED PARTS.
CHECK ALL LIGHTING



RECEIVED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Damage Report Slip

Exit Pass

Job: SHD7134K

JU INCOME

Vehicle No.:

SHD7134K

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard