

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 12.12.2022

Time: 12:21:34

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305539339
REGN NO : SHD7134K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 10.11.2016
DATE/TIME IN : 12.12.2022 12:00
ACCIDENT DATE : 08.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	BUMPER FRT COVER+	1	1,052.20	20.00	841.76	DEF
0002 04-01-0103-0781-A	LAMP ASSY-HEAD LH#	1	1,388.00	20.00	1,110.40	?
0003 04-01-0103-0573-A	PANEL-FENDER LH+	1	663.00	20.00	530.40	X R
0004 04-01-0103-0639-G	BRACKET-FR BUMPER SIDE LH	1	44.80	20.00	35.84	?

SUB-TOTAL : 2,518.40

JOB NATURE

0000 PB	PANEL BEATING	600.00	560
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	40
0003 17-01	CHECK ALL LIGHTING	50.00	X NN

SUB-TOTAL : 1,300.00

NA2 LKK
12/12/2022 1537
LI

3 Days
CHECK ITEM PHOTO
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: