

Our Job Ref No : 305539329
Date 14.12.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. SHA903U

Date of Accident : 11.12.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill 703A INCOME --- SMR6527J
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges _____
 - Total for Part-By-Part Repair Cost** _____
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,000.00
Final Lumpsum Repair cost _____
3. Estimated normal period for repairs: 1 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : _____
Name : JUMANI
Tel : 62148315
Fax : 65468156

Signature : _____
Name : NAZ
Date : 16/12/2022

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305539329
 REGN NO : SHA 903U
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4A)
 DATE OF REGN : 14.01.2020
 DATE/TIME IN : 12.12.2022 15:00
 ACCIDENT DATE : 12.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0302-0897-G	COVER OUTER MIRROR LH	1	141.90 25.00 106.42 X SVL
0002	04-01-0302-0600-G	MIRROR ASSY OUTER REAR VI	1	1,390.10 25.00 1,042.57 / SCR

SUB-TOTAL : 1,148.99

JOB NATURE

0000	PB	PANEL BEATING	120.00	100
0001	SP	SPRAYPAINT CHARGE	120.00	100

SUB-TOTAL : 240.00

TOTAL : 1,388.99

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE :

DATE :

NAZ LKK
 12/12/2022 1611
 LLS
 1 DAY
 AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: