

ASS. REC. BY:

REF:

C12 / 22012446/Kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____ Alan's

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YA 9808T Yr Regn: 04, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Isuzu NPR85 c.c. 2999

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 88241 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JAA NPR8514M 710074

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 195/85R16 (0)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 2 mm R/Bal. 4 4 mm

L/Bal. 2 mm L/Bal. 4 4 mm

D.O.A. 30/11/22 D.O.I. 12/12/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& B

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

10/3 @ 8294.54 Cash

Date/Time, File Pass to? : Prell. Report : Final Report

Date/Time, File Return to?

Days Of Repair: _____ Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$) : Interview (\$) : Tech Invs (\$) : Weekend (\$)

| | |
|-----------------|--|
| Survey Fee: | |
| Transportation: | |
| S + RS. SI | |
| Fuel | |
| Others | |
| TOTAL | |

Report Format : _____ Lump Sum / I.B.I: (\$ _____)

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06714

Vehicle Insured : GBF1221S
Accident Date : 30-Nov-2022

Date : 09-Dec-2022

Our Ref : 022200 (CHINA) / CHAN

PAGE : 1

CHIP HONG FARM PRODUCT
14 WOODLANDS TERRACE
Singapore 738439

*Not authorized
Resurvey BQ prim.
11 days*

ESTIMATED COST OF REPAIR FOR ISUZU NPR85 UH5A3.0 MT D/AB YQ9868T

| | | | |
|-----------------------------------|------------|----------|---|
| 1 pc Bonnet | R | 681.40 | ✓ |
| 1 pc Bonnet "REWARD-NP" sticker | R | 24.00 | ✓ |
| 1 pc Bonnet "ISUZU" emblem | R | 118.00 | ✓ |
| 1 pc O/s corner panel | CM | 165.00 | ✓ |
| 1 pc O/s corner panel top garnish | mtg CM | 26.00 | ✓ |
| 1 pc O/s mirror stand | R | 227.00 | X |
| 1 pc O/s mirror stand top cover | mtg | 16.00 | ✓ |
| 1 pc Front grille chrome assy | CM | 395.00 | ✓ |
| 1 pc N/s round view mirror | mtg | 43.00 | ✓ |
| 1 pc O/s taillamp assy | mtg BQ | 184.00 | ✓ |
| | | 1,879.40 | |
| | Less 15% : | 281.91 | |

| | | | |
|---|----|----------|------|
| | | 1,597.49 | |
| 1 pc Rr o/s door external lock assy | R | 750.00 | sn ✓ |
| 1 pc Rear o/s door rubber capping | CM | 780.00 | sn ✓ |
| 1 pc one protion stainless steel door frame c/w structure bonding and welding | R | 2,400.00 | sn ✓ |
| 1 pc Rear meter bumper, bracket c/w fabrication job and welding | R | 850.00 | sn ✓ |
| 1 pc Rear bumper rubber stopper c/w bracket (set) | CM | 680.00 | sn ✓ |
| 1 pc Rear o/s lower stainless steel door hinge | R | 280.00 | sn ✓ |
| 1 pc Rear o/s mud guard rubber flap and renew rear mudguard assy | R | 280.00 | sn X |
| 1 pc Front no.plate | R | 30.00 | sn X |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBF1221S

Page : 2

To putty and spray replaced parts

800.00 *600*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

700.00 *550*

Total : S\$ 9,147.49

=====

Singapore Dollars Nine Thousand One Hundred and
Forty Seven and Cents Forty Nine Only

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|-------------------------|
| Owner ID Type: | Business |
| Owner ID: | 300L |
| Vehicle Details | |
| Vehicle No.: | YQ9868T |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 09 Dec 2022 |
| Vehicle Make: | ISUZU |
| Vehicle Model: | NPR85UH5A 3.0 MT D/AB |
| Primary Colour: | White |
| Manufacturing Year: | 2021 |
| Engine No.: | 4JJ1170J41 |
| Chassis No.: | JAANPR85HM7100274 |
| Maximum Power Output: | - |
| Open Market Value: | \$40,058.00 |
| Original Registration Date: | 26 Apr 2022 |
| First Registration Date: | 26 Apr 2022 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$2,003.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 25 Apr 2032 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| QP Paid: | \$51,504.00 |
| COE Rebate Amount: | \$41,203.00 |
| Total Rebate Amount: | \$41,203.00 |

The information contained herein is correct as at 09 Dec 2022

OK